

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03264
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Injection ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No. E-1638
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: West Pearl Queen Unit
4. Well Location Unit Letter <u>H</u> : <u>1650</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>East</u> line Section <u>31</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County		8. Well No. 152
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3723' GL		9. Pool name or Wildcat Pearl Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Circulate hole w/+/- 60 bbls mud.
- 3) Tag cement on top of CIBP @ 4700'.
- 4) Perforate @ 1700' & squeeze 50' in & out. Tag @ 1650'.
- 5) Perforate @ 150' & squeeze 50' out and circulate to surface.
- 6) Circulate 10 sx Class C cement @ 60' to surface.
- 7) RD. Install dry hole marker & clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 9/10/03
Type or print name Angie Crawford Telephone No. 432-683-3171

APPROVED BY Harry W. White FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any: _____

SEP 15 2003

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: West Pearl Queen #152

COUNTY: Lea

STATE: NM

HOLE SIZE: 17 1/2"
CASING: 13" @ 102'
CEMENTED WITH: 100% X
CEMENT TOP: Surface

Perf @ 150'

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

Perf @ 1700'

HOLE SIZE: 11"
CASING: 8 5/8" @ 1834'
CEMENTED WITH: Mud
CEMENT TOP: N/A
Pulled

25 sr on top of C18P
C18P @ 4700'

4741' - 52'

4784' - 89'

HOLE SIZE: 8"
CASING: 7" @ 4874'
CEMENTED WITH: 150% X
CEMENT TOP: 2491'

PBTD: 4930'

TD: 4930'