

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-~~2~~3273

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E5886

7. Lease Name or Unit Agreement Name:

West Pearl Queen Unit

8. Well No. 137

9. Pool name or Wildcat
Pearl Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator Xeric Oil & Gas Corporation

3. Address of Operator P. O. Box 352
Midland, TX 79702

4. Well Location

Unit Letter C : 660 feet from the North line and 1980 feet from the West line

Section 32 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU Pulling Unit.
- 2) Circulate hole w/+/- 60 bbls mud.
- 3) Spot 25 sx of Class C cement @ 4650' & tag.
- 4) Spot 25 sx of Class C cement @ 1700'.
- 5) Perforate @ 150' & squeeze 50' out and circulate to surface.
- 6) Circulate 10 sx Class C cement @ 60' to surface.
- 7) RD. Install dry hole marker & clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 9/10/03

Type or print name Angie Crawford

Telephone No. 432-683-3171

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE SEP 15 2003

Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: West Pearl Queen #137

COUNTY: Lea

STATE: NM

HOLE SIZE: 12 1/4"
CASING: 8 5/8" @ 122'
CEMENTED WITH: 90 SX
CEMENT TOP: Surface

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

Perf @ 150'

DV Tool @ 1931' w/ 50 SX
PERFS: TOE 1645'

4785' - 87'

4930' - 32'

PBTD: 4949'

TD: 4985'

HOLE SIZE: 7 7/8"
CASING: 4 1/2" @ 4985'
CEMENTED WITH: 250 SX
CEMENT TOP: 3844'