Form 3160-5 (April 2004)

UNITED STATES Hobbs, NAI 8824)

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMNM 080123

SUNDAT NUTICES AND REPURTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other	WEST CAP QUEEN SAND UNIT 8. Well Name and No.
2. Name of Operator PALISADES ASSET HOLDING COMPANY., LLC	WELL NO 15
3a Address 3b. Phone No. (include area code)	9. API Well No. 30-005-01108
223 W. WALL ST., STE 825, MIDLAND, TEXAS 79701 432-686-7159	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	CAPROCK QUEEN 11. County or Parish, State
330 FNL & 330 FEL SECTION 21, TOWNSHIP 14 SOUTH, RANGE 31 EAST, UNIT LETTER A	CHAVES CO., NEW MEXICO
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	<u>. </u>
Acidize	Well Integrity Other
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requifollowing completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclar determined that the site is ready for final inspection.) PLACED WELL BACK ON PRODUCTION: 3/3/07 - Electrican reviewed installations at well to make operational. 3/25/07 - Prepare to start well 3/26/07 - Turned on well. Appears to have a rod part. Very weight heavy. Would suck & blow or 4/16/07 - Set anchors on well 4/18/07 - MI & RU lucky well service. Rig up to pull rods. Pumped 30 bbls of hot water down the flowline to have hole in same near well head. Stopped hot water treatement. Test the w/rods & pu 3/4" rods & found rods unscrewed. S.D. prepare to TIH, screw into rods, recover pump plunger va/19/07 - Prepare to pump & test. After SDON, TIH w/rods & fishing tools. Catch unscrewed rod 1 1/2" x 16' insert pump. TIH w/2" x 1 1/2" x 16' RWBC (stationary bbl) pump w/ 113-3/4" steel oil unit. Pumped down theg-csg annulus out tubing w/7 bo & flowline appeared to plug. RIg down Load & test to 600#held okay. Rig down & move off 4/20/07 - Tied together flowline after re-routing same 4/21/07 - Finished repairing pumping unit base. Start well producing in the P.M.	a each stroke -csg annulus. Well started circulating. Found imp in hole to 500 #held okay. TOH w/106-w/sv & inspect plgr. at 2650'. Unseat pump & TOH w/rods & 2" x rods & 2-4' & 1-6' 3/4" pony rods. Rig up hot
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	
HERBERT F. BOLES Title MANAGING MEMI	BER
Signature Append & Poles Date	04/23/2007
ACCEPTED FOR RECORD FOR FEDERAL OR STATE OFFICE	USE

(Instructions on page 2)

us Approved Plugging Program!