State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION DIVISIO	Revised 5-27-2004	
DISTRICT I	1220 South St. Francis Dr.	WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240	Santa Fe, NM 87505	30-025-28331	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210		5. Indicate Type of Lease STATE X FEE	
DISTRICT III		STATE X FEE 7	
1000 Rio Brazos Rd, Aztec, NM 87410		or state of the state place.	
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit	
1. Type of Well:	APPLICATION FOR PERMIT" (Form G101) for such proposals.)	Section 34 8. Well No. 127	
Oil Well	Gas Well Other Injector	8. Well No. 127	
2. Name of Operator	- Injection	9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator		10 P. J. Will (0.00)	
HCR 1 Box 90 Denver City, TX	79323	10. Pool name or Wildcat Hobbs (G/SA)	
4. Well Location			
Unit Letter L : 1980	Feet From The South 860	Feet From The West Line	
Section 34	Township 18-S Range	38-E NMPM Lea County	
in the second of the second	11. Elevation (Show whether DF, RKB, RT GR, etc.)	So-E Idahir Eea County	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3625' GL		
Pit or Below-grade Tank Application	or Closure		
Pit Type Depth of Ground	d Water Distance from nearest fresh water well _	Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check	Appropriate Box to Indicate Nature of Notice, Report,	or Other Data	
NOTICE OF INTE		UBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG & ABANDONMENT	
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CE	MENT JOB	
OTHER: Clean out/acid treat	X OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. Kill well. Pull out of hole w/injecti-	on equipment.		
1. Kill well. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4423'. 3. Acid treat well w/4600 gal of 15% PAD acid			
 3. Acid treat well w/4600 gal of 15% PAD acid. 4. Run back in hole w/injection equipment. 			
5. Test casing & chart for the NMOCD			
	Received		
	Received Hobbs		
	Received Hobbs		
Thereby certify that the information above is to	text		
constructed or	True and complete to the best of my knowledge and belief - further ce	rtify that any pit or below-grade tank has been/will be	
I hereby certify that the information above is to constructed or closed according to NMOCD guidelines	text		
constructed or	rue and complete to the best of my knowledge and belief Further ce		
constructed or closed according to NMOCD guidelines SIGNATURE	rue and complete to the best of my knowledge and belief Further ce	tive Associate DATE 05/08/2007	
constructed or closed according to NMOCD guidelines SIGNATURE	rue and complete to the best of my knowledge and belief. Further ce , a general permit or an (attached) altern plan TITLE Administra	tive Associate DATE 05/08/2007	
constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. Jo	rue and complete to the best of my knowledge and belief. Further ce , a general permit or an (attached) altern plan TITLE Administra	tive Associate DATE 05/08/2007	
constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. Jo For State Use Only	rue and complete to the best of my knowledge and belief. Further ce , a general permit or an (attached) altern plan TITLE Administra hnson E-mail address: mendy johnson@oxy.	tive Associate DATE 05/08/2007 com TELEPHONE NO. 806-592-6280	