
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07430	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
	TICES AND REPORTS ON WEI	LLS	7. Lease Name or Unit Agreeme	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
	PPLICATION FOR PERMIT" (Form G1		Section 29	
Type of Well: Oil Well X	Gas Well Other Te	mporarily Abandon	8. Well No. 221	
2. Name of Operator	Gas wen Cine 10	inportarily Abdition	9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323		•••••	
4. Well Location				
Unit Letter F : 2310	Feet From The North	Feet	From The West	Line
Section 29	Township 18-S	Range 38-E	NMPM	Lea County
	11. Elevation (Show whether DF, RK 3653' DF	B, RT GR, etc.)		10 by 18
		<u> </u>		Salamini Maria (Personal Malaina)
Pit or Below-grade Tank Application	or Closure		D' 4 C	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTE	•••	SUBS	SEQUENT REPORT OF	:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	NS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	т ЈОВ	
OTHER:		OTHER: Temporarily		X
12 Describe Proposed or Completed On	erations (Clearly state all pertinent d			starting any
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. RUPU & RU. RU wireline & shoot hole in the @3821'. RD wireline.				
2. ND wellhead/NU BOP w/annular.				
 3. Kill well with 92 bbl of 12.1 mud down casing & 18 bbl 12.1 mud down tubing. 4. POOH & lay down ESP equipment. 				
4. POOH & lay down ESP equipment. 5. RU wireline & set CIBP @4100'. Dump 10' of cement on top of CIBP. 6. Circulate mud out. Test casing. OK				
o. Circulate mad out. Test casing. Ok.				
7. ND BOP/NU wellhead. 8. Test casing to 540# for 30 minutes & chart for the NMOCD.				
9. RDPU & RU. Clean location				
Well is temporarily abandoned. RUPU 04/30/2007 RDPU 05/03/2007				
wen is temporarily doubtened.			-01	.00
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved				
plan plan				
SIGNATURE	WARYAN	TITLE Administrative		05/10/2007
	ohnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280 MAY 1 2007
For State Use Only Hart 1 3 2007				
APPROVED BY Jay W. W. OC FIELD REPRESENTATIVE IT/STAFF MANAGER MAY 1 & 2007				
CONDITIONS OF APPROVAL IF ANY:				
This Approval of Temporary 5/3/12 Abandonment Expires				
Abandonment Expires				



and the same and t