Submit 3 Copies To Appropriate District Office District II 1301 W. Grand Ave. State NM 88210 District III 1000 Rio Brazos Rd., Aztec NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other P&A 2. Name of Operator	Form C-103 May 27, 2004 WELL API NO. 30-025-37259 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Chesney State Unit 8. Well Number 2 9. OGRID Number 025575 10. Pool name or Wildcat Sand Springs; Atoka-Morrow (Gas)
4. Well Location Unit Letter O: 750 feet from the South line and 1	650 feet from the <u>East</u> line
Section 2 Township 11S Range 35E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Lea County
4058' GR	
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS.☐ P & A ☐ CASING/CEMENT JOB ☐	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. 4-24-07 MIRU plugging company. POOH w/tubing. RIH w/tubing to 9054'. 4-25-07 RIH w/CIBP and set @ 9600'. Dumped 35' Class "H" on plug. RIH w/tubing to 6700'. 4-26-07 Circulated hole w/plugging mud. Spot 25 sx @ 6700'. PUH to 4220' and spot 25 sx. 4-27-07 RIH and tag @ 3852'. POOH. RIH and perforated @ 2100'. POOH. RIH w/packer. Held 1000#. RIH to 2156' open-ended and spot 25 sx. 5-1-07 RIH and tagged @ 1960'. POOH. RIH and perforated @ 472'. POOH. RIH w/packer and tubing. Held 1000#. RIH to 522'. Spot 25 sx. POOH and WOC 5-3-07 TIH and tagged @ 334'. POOH. ND BOP and NU WH. RIH to 64' Circulated 15 sx to surface. RD equipment. Dig out WH. Cut off WH. Installed dry-hole marker. Cut off anchors. Cleaned up location.	
WELL IS PLUGGED AND ABANDONED. FINAL REPORT.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE TITLE Regulatory Compliance Technician DATE 5-7-07	
Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471 For State Use Only APPROVED BY: DATE TITLE TITLE TO THE TO T	