Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OV. GOVGDDVATION DWWGON	WELL API NO. 30-025-09214
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. 34227
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Seven Rivers Queen Unit
1. Type of Well: Oil Well Gas Well Other - Injection		8. Well Number 43
2. Name of Operator Arena Resources Inc.		9. OGRID Number
3. Address of Operator		220420 10. Pool name or Wildcat
4920 S. Lewis, Suite 107, Tulsa, OK 74105		Seven Rivers Queen
4. Well Location		
Unit Letter C: 660	0feet from the <u>North</u> line and <u>198</u>	0 feet from the <u>West</u> line
Section 2	Township 23S Range 36E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐  TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐  PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐		
OTHER:	CI OTUED:	
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  The state of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Casing bad from 592 -721. Spot 100 sxs cement across bad casing and attempted to squeeze.		
Drilled out cement. Casing will hold 300 psi for 30 min. When testing casing to 500 psi, it lost 100 psi in the first 20 minutes.		
Perfs: 3668 to 3777'		
Drill out CIBP. Clean out to PB7	ΓD, acidize. 29303	
128255		
Convert well to active producer.		
	100 100 100 100 100 100 100 100 100 100	3 🚣 🦁
	72	70/
	ેં <u>ટ</u> ્ર	
	N. 21. 21. 91. 9	17/6
	e e e e e e e e e e e e e e e e e e e	
I hereby certify that the information ab	ove is true and complete to the best of my knowled	ige and belief. I further certify that any pit or below-
grade tank has been/will be constructed or cle	osed according to NMOCD guidelines , a general permit	or an (attached) alternative OCD-approved plan .
SIGNATURE In Inc.	TITLE Production Superv	visor DATE 5-10-07 .
8		J-10-0/
Type or print name Danny M. Palm	ner E-mail address: dpalmer@arenareson	AANIACEP
For State Use Only  OC DISTRICT SUPERVISOR/GENERAL MANAGER  MAY 2 1 2007		
APPROVED BY: The US	Ellens TITLE	DATE
Conditions of Approval (if any): Casing still needs to be repaired before production.		
to the state of th		