Submit 3 Copies To Appropriate District Office	State of New 1	Mevico	<b>-</b>
District I	Energy, Minerals and N		Form C-103
1625 N. French Dr., Hobbs, NM 88240 District II		aratai 1000000000	Revised June 10, 2003 WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-35631
District III			5. Indicate Type of Lease
District IV Santa Fe. NM 87505			STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505		07303	6. State Oil & Gas Lease No.
	C AND DEDODTE ON WEST		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	TION FOR PERMIT" (FORM C-101	) FOR SUCH	N-112- 01
1. Type of Well:			Nellie 21  8. Well Number
Oil Well Gas Well Other			
2. Name of Operator			001
Chesapeake Operating, Inc.			9. OGRID Number
3. Address of Operator			147179 10. Pool name or Wildcat
P. O. Box 18496, Oklahoma City, OK 73154-0496			1.77
4. Well Location			Lovington Upr Penn NE
Unit Letter I 19	980 foot from the		
omt Botton_i	feet from the Sou	thline and	660 feet from the East line
Section 21	Township 16S	Range 37E	ND CDL C
1	1. Elevation (Show whether D	R RKB RT GR etc.)	NMPM Lea County
	CR • 3701 •	·	
12. Check App	propriate Box to Indicate	Nature of Notice.	Report or Other Data
NOTICE OF INTE	·N I I ( ) ( ) ·	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK KIND P	LUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON TI C	HANGE PLANS	0014145110555	
		COMMENCE DRIL	LLING OPNS. PLUG AND
	IULTIPLE	CASING TEST AN	ABANDONMENT
	OMPLETION	CEMENT JOB	
OTHER:	П	OTHER:	_
<ol><li>Describe proposed or complete</li></ol>	d operations. (Clearly state al		give pertinent dates, including estimated date
of starting any proposed work).	SEE RULE 1103. For Multi	ple Completions: Atta	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
1) MIRU Service Rig	2) POOH w/pump, r	ods & tubulars	
3) Perf Strawn 11442-64' OH N/D log dated 11/1	W/4 SPF, 23 gram ch	ig, 60° phasing	, correlate to the
4) Set a CIBP at 11,494'	5/01		
5) RIH w/treating packer	to 11400', load & t	est backside to	0.1000# 08293037.
o) Bullhead 4000 gal 15%	retarded NEFe acid.	launch 125 bal	ll sealers during job, displace
to berrs wirease Mtr.			7.50 W
7) Wait on acid 3 hours			/s sqqoH
8) Swab back to clean up	hole, POOH w/packer	•	YES IN ED
9) RIH w/prod. tbg, set	SN & PS as low as po	ssible, PWOP	13 con 439
			Hopps SS SS SEP 2003 SS
		,	(2)
hamby and Call and a	<u></u>		
hereby certify that the information abov	e is true and complete to the l	est of my knowledge	and belief.
SIGNATURE Darbase J. Ra	1		- 4
<i>y</i>		gulatory Analys	DATE 09/11/03
Type or print name Barbara J. Ba	1e E-mail a	ddress:	Talantan 37 (405)040
This space for State use)			Telephone No. (405)848-
ADDDD DIE Y	1,1,0		Orn :
APPPROVED BY are to Conditions of approval, if any:	ルルルP TOTCE	D REPRESENTATIVE	II/STAFF MANADATE SEP 1 6 2003
N : / I approval, if any:			