State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-07-	470
DISTRICT II	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agree	ment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Uni	t ·
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C101) for such proposals.)			Section 30	
1. Type of Well: Oil Well Gas Well Other Injector			8. Well No. 411	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			110003 (0/0/1)
4. Well Location	1			/
Unit Letter A : 330	Feet From The North	Feet	From The East	Line
Section 30	Township 18-S	Range 38-E	NMPM	Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3659' GL				
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIN	G CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI	NS. PLUG & A	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	T JOB	
OTHER: Plug back/acid treat	X	OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1 William II Doll in least an aminor and			180	
 Kill well. Pull injection equipment Run bit & scraper to PBTD @4290 			100	
3. Plug back w/cement to 4260°.	•			
4. Acid treat well w/15% HCL.				March 1
5. Run back in hole with injection equ			$p_{J_{i}G_{i}}$	
6. Test casing and chart for the NMO7. Return well to injection.	CD.			
7. Return wen to injection.				gg ²
PM	x - 204			
I hereby certify that the information above is	true and complete to the best of my know	vledge and belief. Ifurther certify t	hat any pit or below-grade tank	has been/will be
constructed or closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	1
700		_ plan `		·
SIGNATURE MANAGEMENT	Wohman	TITLE Administrative	Associate DAT	E 05/23/2007
TYPE OR PRINT NAME Mendy(A). Jo	hnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO	806-592-6280
For State Use Only OC FIELD REPRESENTATIVE IL/STAFF MANAGER				
APPROVED BY Laylu and TITLE DATE MAY 2 5 2007				
CONDITIONS OF APPROVAL OF NY:				