

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36939
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-22080
7. Lease Name or Unit Agreement Name: BULLRED 6 STATE
8. Well Number 1
9. OGRID Number 778
10. Pool name or Wildcat CORBIN: ABO 13150

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2. Name of Operator BP America Production Company
3. Address of Operator P.O. Box 1089 Eunice NM 88231	4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>495</u> feet from the <u>EAST</u> line Section <u>6</u> Township <u>18S</u> Range <u>34E</u> NMPM County <u>LEA</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4082' GL	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04/27/05 - Chris Williams of NMOCD gave verbal approval for procedure on 4/27/05 @ 3:30 pm.
MIRUPU. RIH w/ P&A assy. Tag @ 9400'. PU & LD 5 jts DP to 9200'. Pmp 227 sks class H cmt followed by 1 bbl wtr & 115.5 bbls. mud. Pull up to 8366' & circ. WOC.
04/28/05 - Tag cmt @ 8400'. PU & LD 3 jts DP to 8300'. Pmp 190 sks class H cmt followed by 1 bbl wtr & 106 bbls mud. POH 8 stands DP & circ. Tag cmt @ 7800'. POH to 4854'. Pmp 26 sks class C cmt followed by 1 bbl wtr & 60 bbls mud. POH & circ. Tag cmt @ 4754'. POH to 3064'. Pmp (2 stgs) 406 sks class C cmt followed by 2 bbls wtr & 51 bbls mud. POH & circ. Tag cmt @ 1500'.
(See continued on reverse side.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Nicki Owens TITLE Administrative Assistant DATE 5/22/07

Type or print name Vicki Owens

E-mail address: owensv12@bp.com
Telephone No. 505-394-1650

For State Use Only

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER JUN 04 2007

Conditions of Approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

04/29/05 – POH to 210'. Pmp top plug w/ 64 sks class C cmt followed by 1 bbl
wtr. Circ to surface. ND P&A assy. Cut off 8 5/8" csg. Cut off 13 3/8" csg.
Remove WH. Install P&A marker.
Well P&A'd 04/29/05.