Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Energy, Minerals and Natural Resources May 27, 2004 Office District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-09866 District II OIL CONSERVATION DIVISION 5. Indicate Type of Lease 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr. District III FEE 😠 STATE [] Santa Fe, NM 87505 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 6 State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PRIEST DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 9. OGRID Number 2. Name of Operator 236378 SABER RESOURCES, LLC 10. Pool name or Wildcat 3. Address of Operator 400 W. Illinois. Suite 950, Midland, 4. Well Location feet from the \ 🔼 NORTH One and 1980 660 feet from the line Unit Letter \_\_\_\_ 15 S Range **NMPM** TF.A Township 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3806' 6R Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well \_\_\_\_ \_\_\_ Distance from nearest surface water \_\_\_ Pit type STEEL Depth to Groundwater \_ \_bbls; Construction Material . Below-Grade Tank: Volume\_\_\_\_\_ Pit Liner Thickness: \_ 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON [ ALTERING CASING ... PERFORM REMEDIAL WORK REMEDIAL WORK COMMENCE DRILLING OPNS. **PLUG AND** X **CHANGE PLANS TEMPORARILY ABANDON ABANDONMENT** CASING TEST AND **MULTIPLE** PULL OR ALTER CASING COMPLETION **CEMENT JOB** Approved as to plugging of the Well Bore. Liability under bond is retained until OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including extinated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5-15-07 Tag CIBP @9,125'. Circulate hole w/mud. Spot 25 sx. cmt. @9,125'. Spot 25 sx. cmt. @6,000'. 5-16-07 Perf. 4 holes @4,850'. Set pkr. @4,500'. Sqz. 50 sx. cmt. Tag plug @4,702'. Perf. 4 holes @2,235'. Set pkr. & sqz. 50 sx. cmt. 5-17-07 Tag & plug @2,075'. Perf. 4 holes @405'. Pump 125 sx. cmt. down 5 1/2" surf. out of 8 5/8" csg. Leave 5 1/2" full of cement. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be distructed or closed according to NMOCD guidelines \_\_\_\_\_, a general permit \_\_\_\_\_ or an (attached) alternative OCD-approved plan \_\_\_\_\_ P & A Asst. Supv. DATE\_ TITLE\_ SIGNATURE. E-mail address: Type or print name CARY EGGLESTON Telephone No. 432-685-0169 For State Use Only Tange Win OC FIELD, REPRESENTATIVE II/STAFF MANAGER DATE APPROVED BY Conditions of Approval, if an