2424 300 705

	1
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II OII CONSERVATION DIVISION	30-025-10692
District III 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	685270
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	SKELLY PENROSE "A" UNIT
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	8. Well Number
Oil Well Gas Well Other INJECTION WELL	46
2. Name of Operator	9. OGRID Number
1	000873
CIMAREX ENERGY CO. OF COLORADO ATTN: ZENO FARRIS  3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 140907, IRVING, TEXAS 75014-0907	IANGLIE MATTIX 7 RIVERS-Q-GRAYBURG
4. Well Location	I LANGLIE MATILA / KIVERS-U-GRAIBURG
T. Well Execution	
Unit Letter B: 660 feet from the NORTH line and	1980 feet from the EAST line
Section 09 Township 23S Range 37E	NMPM County <b>LEA</b>
11. Elevation (Show whether DR, RKB, RT, GR, e	etc.)
3,298' GR	
Pit or Below-grade Tank Application or Closure 🔀	
Pit type Depth to Groundwater 125' Distance from nearest fresh water well * D	istance from nearest surface water*
Pit Liner Thickness: mil Below-Grade Tank: Volumebbk; Construct	I and the second se
THE THERMESS,	on machine
12. Check Appropriate Box to Indicate Nature of Notice  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CEMENT JOB  13. DEEGINNING OF PLUG GINCOOP Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.	ING ONS. FLUG AND ABANDONMENT CONTROL OF THE PROPERTY OF THE P
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION FULCE  COMPLETION  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CHANGE OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF MULTIPLE COMPLETIONS: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450'; WC & TAG TO THE PLUG @ 1,236'; WC & TAG TO THE PLUG @ 1,	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  S. ANYONE ON JOB LOCATION HAS THE  SSX CEMENT PLUG F/2450-2350  OP OF CMT. PLUG. B.O.S.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  THE OIL CONSERVATION DIVISION CEMENT JOB  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CEMENT JOB  13. DESEGNATING OF PLUGCING OF Explorate all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF CIBP @ 3,450'. MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO THERE.	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  SON CEMENT PLUG.  BY OF OMT. PLUG.  BY OF OMT. PLUG.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION FILE  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE COMPLETION  OTHER:  13. DESCRIPTING OF PLUG CINC OF CLERTY, state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIEP @ 3,450'; CIRC. WELL W/ PXA MID.  2) MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF CIEP @ 3,450'; MC & TAG TO ALL OF COMPLY WITH TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WC & TAG TO BERF. & ATTEMPT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG TO MIX & FILL ALL CASING ANNULUS W/ 25 SX. CMT. PLUG @ 63'-3'	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE STANDARD POF OMT. PLUG.  DE OF OMT. PLUG.  DE OF OMT. PLUG.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLI  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CHARLES AND CEMENT JOB  OTHER:  13. DEEGINNING OF PLUGGING OF Etayly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PIMP A 25 SX. CMT. PLUG ON TOP OF CIBP @ 3,450'; MC & TAG TO ALL CASING ANNULUS W/ 25 SX. CMT. SURF. PLUG @ 63'-3'  4) PERF. & ATTEMPT TO SQZ. A 100 SX. CMT. PLUG @ 1,75'; WCC & TAG TO MIX & FILL ALL CASING ANNULUS W/ 25 SX. CMT. SURF. PLUG @ 63'-3'  7) DIG OUT & CUT OFF WELLHEAD 3' B.G.L.; WELD STEEL PLATE ON CASING	ING CONS. TO FLUG AND ABANDONMENT ABANDONMENT ABANDONMENT OF PROPOSED COMPLETE OF CATION HAS THE SOLVENT PLUG. B.O.S.  OP OF CMT. PLUG.  OP OF CMT. PLUG.  OP OF CMT. PLUG.  OS & SET DRY HOLE MARKER.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION COMPLETION  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE COMPLETION  OTHER: 13. DESCRIPTION DIVISION COMPLETION  OTHER: 14. DESCRIPTION OTHER: COMPLETION  OTHER: 15. DESCRIPTION OF COMPLETION OTHER: COMPLET	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  S. ANYONE ON JOB LOCATION HAS THE  SSA CEMENT PLUG.  BY OF CMT. PLUG.  BY OF CMT. PLUG.  BY OF CMT. PLUG.  CASE SET DRY HOLE MARKER.  In the design of proposed completion of the completion of t
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CHEEN TO THE COMPLETION  OTHER:  13. DEEGINNING OF PLUGGING OF Eleging state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG & 1	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CHEEN TO THE COMPLETION  OTHER:  13. DEEGINNING OF PLUGGING OF Eleging state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG & 1	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CHEEN TO THE COMPLETION  OTHER:  13. DEEGINNING OF PLUGGING OF Eleging state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG & 1	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CEMENT JOB  OTHER:  13. DEEGINNING OF PLUGGING OF CERTY state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CEMENT JOB  OTHER:  13. DEEGINNING OF PLUGGING OF CERTY state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DELLE  PULL OR ALTER CASING MULTIPLE COMPLETION  THE OIL CONSERVATION DIVISION MUST  OTHER: BE NOTIFIED 24 HOURS PRIOR TO THE CEMENT JOB  OTHER:  13. DEEGINNING OF PLUGGING OF CERTY state of pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attactor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT & SAFETY REGULATION AUTHORITY TO SHUT DOWN UNSAFE WORK.  1) TAG EXISTING CIBP @ 3,450'; CIRC. WELL W/ PXA MUD.  2) MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF CIBP @ 3,450' MAP 2.  3) PERF. & ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1,236'; WCC & TAG TO GOVERNMENT TO SQZ. A 100 SX. CMT. PLUG @ 175'; WCC & TAG	ive pertinent dates, including estimated date h wellbore diagram of proposed completion  IS. ANYONE ON JOB LOCATION HAS THE  OP OF CMT. PLUG.  OP OF CMT. PLUG.  SS & SET DRY HOLE MARKER.  dge and belief. I further certify that any pit or belowth or an (attached) alternative OCD-approved plan

JUN 1 2 2007

## Prize Operating Company UPDATE 11-29-01 CURRENT COMPLETION

## WELLBORE DATA AND SKETCH

Wett: Skelly Penrose A Unit # 046	FIELD: Langlie Mattix	Date:11/30/01
County: Lea	State: New Mexico	Status: Injection
Directions:	Location: 660' FNL & 1980' FEL	Survey: Sec 09, Township 23S, Renge 37E
PERMANENT WELLBORE DATA	API # 30-025-10892	DATA ON THIS COMPLETION
Elevation: GL; 3298'	Current Completion	Leese No. 301130-037
DF: 3310'		Spud: 06/23/37 TD: 3642'
KB:		RR: FP:
TOC 16" @ Surface		Compl: 08/13/37
		Cum.:
16", 70# @ 127' in 17 1/2" hole		Current Prod: Injection Well
Cemented w/ 75 sx. To Surface		
TOC 8 5/8 @ 829' calculated		
/		
8 5/8" 28# set @ 1136 w/ 100 sx cement		
Calc TOC @ 2251'		
		02/75 repair casing leak @ 2800' sqz'd w/250 sx
		103 ITS 2-3/8 CMT.
		LINED TEG. IN WELL
ıblıng:		
2 7/8 " Tubing to below packer @ 3197"		
2 170 Tribbilg to below packer (@ 3197		
		- 489107
d String:		(45)
		- A (
		/12/
		Packer set @ 3210
		(5) AL(6)
	TOTAL NOTICE AND ADDRESS OF THE PARTY OF THE	Hope to
	RESIDENCE PROFESSION AND AND AND AND AND AND AND AND AND AN	
ing:		09/27 51 0402 0000
7" , 20# set @ 3451'	4°018P	08/37 perfd 3493-3830 11/67. Convert to injection
Cemented w/ 200 sx		1 I/O/. CONVERT TO INJECTION
100 00		08/72 Set 5" liner. Cmt in place, per 35/8-3524"
	<b>3 E</b>	acidized w/1000 gal 15%
		02/75 perforated 3484-88, 3505-08, 3516-20,
r:		3530-3540, 3582, 3598-3598, 3606 3624
5", OD liner set from 3318' - 3642'		total of 36 shots, acidized w/8000 gal 15%
AFOC - OLGO USU SEE SEE		
90	ITD: 3,642'	
	: 3642 <sup>1</sup>	, ,
TU	, JUNE	TAE