Submit 3 Copies To Appropriate District Office <u>District I</u>	e Energy, Minerals and Natural Resources			Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERV 1220 South Santa Fe	St. Fran	ncis Dr.	WELL API NO. 30-025-02643 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name: Jack Markham
1. Type of Well: Oil Well Gas Well Other				8. Well No. 1
2. Name of Operator				9. OGRID Number
Penroc Oil Corporation 3. Address of Operator				17213 10. Pool name or Wildcat
PO Box 2769, Hobbs, NA	4 88241-2769			Bough; Permo Penn
4. Well Location				
Unit Letter O: 660 feet from the South line and 1980 feet from the East line Section 11 Township 9S Range 35E NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4145				
Pit or Below-grade Tank Application or Closure 57EEL PIT				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
<u> </u>	Appropriate Box to Ind			
	•••	iicaic iva	luie of Nonce, N	Report of Other Data
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING	CHANGE PLANS		SUBS REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	LING OPNS. ☐ PAND A 🔯
OTHER:			OTHER:	П
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 6/5/07 MIRU. NU BOP. RU wireline, RIH w 5 1/2 gauge ring. Stack out @ 7900'. POH SDFN 				
6/6/07 RIH w/ 5 1/2 CIBP and set @ 7700'. Lost setting tool in hole. WIH w/ fishing tool and tbg. caught setting tool, POH. 6/7/07 RIH w/ tbg. open ended, to 7700'. Pump 60 bbls of mud laiden fluid. Spot 10 sx cement on top of CIBP. POH to 4300'. SDFN. 6/8/07 Load hole w/ mud laiden fluid. Spot 40 sx cement plug @ 4300'. WOC 4 hrs. Tag plug @ 4050. POH to 2240'. Spot 30 sx				
cement plug @ 2240 to 1937'. POH to 520' Spot 30 sx cement plug. WOC 4 hrs. Tag plug @ 355'. POH to 60 ft. Circulate 20 sx cement plug to surface. Cut off wellhead, dead men. Weld on Dry Hole Marker, Rig down move off.				
Fg				
Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.				
SIGNATURE MORE	- xfect	TITLE /	resident	DATE 6/12/07
has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE DATE SIGNATURE SIGNATURE DATE SIG				
APPROVED BY Conditions of Approval (if any):	William	TITLE_	Wit Supe	win DATE 6/14/07