

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-05871
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J.W. Cooper "G" (29121)
8. Well Number 3
9. OGRID Number 495
10. Pool name or Wildcat Monument; Paddock (47080)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. Box 840 Seminole, Texas 79360	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>West</u> line Section <u>3</u> Township <u>20S</u> Range <u>37E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3559'</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Shut In for Evaluation ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03 thru 8/6/2003

MIRU Tyler well service. TOH w/rods & pump. Released pkr & installed BOP. Removed pkr & TIH w/tbg. Pumped 22 bbls hot oil w/paraffin solvent down tbg. TOH w/tbg & CI BOP. MIRU Rotary Wireline. TIH w/4 1/2" CIBP & set @ 6400'. TIH w/3" dump bailer and dumped 35' cement on CIBP. TIH w/2 3/8" SN & tbg and put SN @ 6350'. Circulated clean. TOH w/tbg & added 16' of SN @ 5366'. MIRU BJ Svs. Acidized from 5366'-5240' w/7 bbls of 15% NEFE HCL. TOH w/tbg. TIH w/3 1/8" csg guns & perf'd 4 1/2" csg from 5374'-5378'. TIH w/2 3/8" tbg & pkr set @ 4450'. MIRU BJ Svs & acidized Paddock zone from 5874'-5878' w/1000 gals of 15% NEFE HCL acid. Swabbed well. Tested, held OK. Released pkr & TOH w/ tbg. Installed safety valve & closed in. MIRU Baker Wireline. TIH w/3 1/8" csg guns & perf'd csg from 5354'-5364' w/4 SPF. TIH w/tbg & set pkr @ 5289'. MIRU BJ Svs and pumped 19 bbls acid to end of tbg, closed bypass on pkr, cont'd pumping 17 bbls acid. Swabbed well. Released pkr & TOH w/tbg & pkr. TIH w/tbg & straddle pkr set @ 5351', bottom of pkr @ 5365'. Swabbed well. TOH w/tbg & pkr. TIH w/RBP, tbg & pkr. RBP set @ 5367'. Pkr set @ 5352'. Swabbed well. Released pkr & tagged TOC above CIBP @ 6360'. Circulated clean. RDMO pulling unit and cleaned location. Well closed in for evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Moore TITLE Prod Acct Tech

Type or print name Carol J. Moore

cmoore@hess.com

Telephone No. (432)758-6738

(This space for State use)

APPROVED BY Larry W. Wink TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE 9/15/2003  
Conditions of approval, if any:

