Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103
Office District I	Energy, Minerals and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-23213
1301 W. Grand Ave., Artesia, NM 88210	District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III	1220 South St. Fran	ncis Dr.	STATE FEE S
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	A A A A A A A A A A A A A A A A A A A		
	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	S TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	, and the second
DIFFERENT RESERVOIR. USE "APPLICAT" PROPOSALS.)	ION FOR PERMIT" (FORM C-101) FO	OR SUCH	Langlie Mattix Penrose Sand Unit
	s Well Other Water	injection	8. Well Number 171
2. Name of Operator			9. OGRID Number 240974
LEGACY RESERVES OPERATING	LP		10 P. I. Will-4
3. Address of Operator	02		10. Pool name or Wildcat Langlie Mattix 7Rvs-Qn-Gb
PO BOX 10848, MIDLAND, TX 7970	J2		Langue Wattix / RVS-Qu-Ob
4. Well Location		1 0001 6 46 4	NIEGT L'
	eet from the <u>NORTH</u> line and		ı
Section 26		ange 37E	NMPM County LEA
	1. Elevation (Show whether DR)	, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application ☐ or C	/		
Pit type Depth to Groundwater		water well Dist	tance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume		onstruction Material
12. Check App	propriate Box to Indicate N	lature of Notice, i	Report of Other Data
NOTICE OF INTE	ENTION TO:	SUBS	SEQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON 🔲 (CHANGE PLANS	COMMENCE DRIL	.LING OPNS.□ P AND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB
OTUED.	П	OTHER:	П
OTHER:	ed operations (Clearly state all		give pertinent dates, including estimated date
of starting any proposed work)	SEE RULE 1103. For Multip	le Completions: Atta	ach wellbore diagram of proposed completion
or recompletion.	•		s to plugging of the Well Bore.
		Liability und	der bond is retained until
SEE ATTACHED PLUGGED W	ELLBORE DIAGRAM	surface resto	ration is retained until pration is retained until pration is completed ugging equipment.
		y meeting. MIRU	Triple ing #22plated ugging equipment.
Set steel working pit. SD for weeke		1 1 1 1 1	to NILDOD and DOOL on/ took in a
06/11/07 Monday Contacted NM	IOCD, Buddy Hill, ND Kect		
RIH W// AMAC HIMI TOGESPILLIBE TO 3 A			
	400'. RU cementer and set C	CIBP @ 3,400°. Cir	rculated hole w/ mud and pumped 25 sx C
cmt 3,400 – 3,054'. Contacted NM	400'. RU cementer and set COCD, Gary Wink. PUH w/t	CIBP @ 3,400'. Cirubing to 2,463' and	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'.
cmt $3,400 - 3,054$ '. Contacted NM POOH w/ tubing. RIH w/ $4\frac{1}{2}$ " AD-	400'. RU cementer and set C OCD, Gary Wink. PUH w/ t -1 packer, set packer @ 885'.	CIBP @ 3,400'. Cirubing to 2,463' and RU wireline lubri	rculated hole w/ mud and pumped 25 sx C l pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'.
cmt 3,400 – 3,054'. Contacted NM POOH w/ tubing. RIH w/ 4½" AD-RD wireline w/ packer @ 885'. Est	400'. RU cementer and set C OCD, Gary Wink. PUH w/ t -1 packer, set packer @ 885'.	CIBP @ 3,400'. Cirubing to 2,463' and RU wireline lubri	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'.
cmt 3,400 – 3,054'. Contacted NM POOH w/ tubing. RIH w/ 4½" AD-RD wireline w/ packer @ 885'. Est SDFN.	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1,	CIBP @ 3,400'. Cipubing to 2,463' and RU wireline lubri 200 psi. Squeezed	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi.
cmt 3,400 – 3,054'. Contacted NM POOH w/ tubing. RIH w/ 4½" AD-RD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubrication.	CIBP @ 3,400°. Citubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (rculated hole w/ mud and pumped 25 sx C l pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'.
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" AD-RD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full retu	CIBP @ 3,400°. Cinubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (crns in 4½ x 8%°. I	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" AD-RD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full retu	CIBP @ 3,400°. Cinubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (crns in 4½ x 8%°. I	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing.
cmt 3,400 – 3,054'. Contacted NMi POOH w/ tubing. RIH w/ 4½" AD- RD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surface	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (crns in 4½ x 8½°. It is in 4½ x 8½°. Pose in 4½ x 8½°. Pose in 4½ x 8½°.	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing.
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surfaced dry hole marker, backfilled	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar.	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. OOH w/ packer. Topped off wellbore w/
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information about the content of the con	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surfacted dry hole marker, backfilled ove is true and complete to the between the surface of the surface over the sur	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar.	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or below-
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information about the content of the con	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surfacted dry hole marker, backfilled ove is true and complete to the between the surface of the surface over the sur	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar.	rculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. OOH w/ packer. Topped off wellbore w/
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborgrade tank has been/will be constructed or flow	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surfacted dry hole marker, backfilled ove is true and complete to the bested according to NMOCD guidelines	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (cms in 4½ x 85%". For in 4½ x 85%". Pod cellar. est of my knowledge , a general permit	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or below-
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborgrade tank has been/will be constructed or slope.	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surfacted dry hole marker, backfilled ove is true and complete to the besed according to NMOCD guidelines. TITLE_J.	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (crns in 4½ x 85%". For in 4½ x 85%". Pod cellar. est of my knowledge	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE 06/13/07
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborg rade tank has been/will be constructed or do SIGNATURE	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surface and dry hole marker, backfilled ove is true and complete to the best according to NMOCD guidelines TITLE_J. E-mail address	EIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar. est of my knowledge	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE 06/13/07 s.com Telephone No. 432-687-1994
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborgrade tank has been/will be constructed or slope.	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surface and dry hole marker, backfilled ove is true and complete to the best according to NMOCD guidelines TITLE_J. E-mail address	EIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar. est of my knowledge	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE_06/13/07 s.com Telephone No. 432-687-1994
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborgrade tank has been/will be constructed or flow SIGNATURE Type or print name For State Use Only	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surface and dry hole marker, backfilled ove is true and complete to the best according to NMOCD guidelines TITLE_J. E-mail address	CIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt (crns in 4½ x 85%". For in 4½ x 85%". Pod cellar. est of my knowledge	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE 06/13/07 s.com Telephone No. 432-687-1994
cmt 3,400 – 3,054'. Contacted NMPOOH w/ tubing. RIH w/ 4½" ADRD wireline w/ packer @ 885'. Est SDFN. 06/12/07 Tuesday PUH w/ packet 413', POOH w/ wireline. Establish RIH w/ packer to 30', and circulated cmt. RDMO. Cut off wellhead & anchors, installed I hereby certify that the information aborg rade tank has been/will be constructed or do SIGNATURE	400'. RU cementer and set COCD, Gary Wink. PUH w/t-1 packer, set packer @ 885'. tablished rate of 1 BPM @ 1, er to 90'. NU wireline lubricated rate of 1 BPM w/ full returned 130 sx C cmt 400' to surface and dry hole marker, backfilled ove is true and complete to the best according to NMOCD guidelines TITLE_J. E-mail address	EIBP @ 3,400°. Cirubing to 2,463° and RU wireline lubri 200 psi. Squeezed ator. Tagged cmt @ rns in 4½ x 85%°. For in 4½ x 85%°. Pod cellar. est of my knowledge	reculated hole w/ mud and pumped 25 sx C d pumped 25 sx C cmt 2,463 – 2,118'. cator. RIH, perforated casing @ 1,250'. 45 sx C cmt @ 1,250', ISIP @ 900 psi. @ 1,050'. PUH and perforated casing @ RIH w/ tubing, POOH laying down tubing. DOH w/ packer. Topped off wellbore w/ and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan . E. (Triple N Services) DATE_06/13/07 s.com Telephone No. 432-687-1994

PLUGGED WELLBORE SKETCH Legacy Reserves Operating

	Legacy Re
RKB @ DF @ GL @ 3,326'	
	130 sx C cmt 413' to surface Perforated @ 413' and circulated cmt to surface.
	Top of salt @ 9-5/8" 36# @ 1,117', circulated Perf/sqz'd 45 sx C cmt 1,250 -1,050' TAGGED
	4-1/2" TOC 1,900 calc. W/ 70% excess Base of Salt @
	25 sx C cmt 2,463 – 2,118'
	Circulated plugging mud 25 sx C cmt 3,400 -3,054'
	Set CIBP @ 3,400'
	Penrose perfs 3,496-3,654

PBTD: 3,660' TD: 3,700' Date: June 13, 2007

Lease & Well No. : Legal Description : Langlie Mattix Penrose Sand Unit No. 171 840' FNL & 990' FWL, D, Sec. 26, T22S, R37E

State: New Mexico

County:

nty: Lea Si
1: Langlie Mattix-Penrose

Date Spudded : API Number :

Status:

Rig Released: 30-025-23213

Plugged 06/12/07

TRIPLE N
SERVICES INC.

PLUGS SET 06/06/07 - 06/12/07

- 1) Set CIBP @ 3,400'
- 2) 25 sx C cmt 3,400 -3,054'
- 3) 25 sx C cmt 2,463 2,118'
- 4) Perf/sqz'd 45 sx C cmt 1,250 -1,050' TAGGED
- i) 130 sx C cmt 413' to surface

Formation Tops: Rustler Salado

Yates Seven Rivers

Queen Grayburg

San Andres



7" 22# N-80 @ 3,399' cmt'd w/ 925 sx