Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103 Revised March 25, 1999			
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL API NO.			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-24899 5. Indicate Type of Lease			
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE S FEE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505			6. State Oil & Gas Lease No. LG 1736			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name:			
1. Type of Well: Oil Well ☑ Gas Well ☐ Other				Hugh 689-C			
2. Name of Operator				8. Well No.			
BTA Oil Producers				2			
3. Address of Operator				9. Pool name or Wildcat Bagley N. Permo Penn			
104 S. Pecos, Midland, TX 79701 4. Well Location				Bagiey N. Felillo Felill			
. Wen Beethen				3200	L	;-	
Unit Letter K :	feet from the	sou sou	<u>th</u> line and	<u>2080</u> f	eet from the <u>we</u>	est line	
Section 6	Township	12S	Range 33E	NMPM	I Lea C	County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)							
4292' GL							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\boxtimes	REMEDIAL WOR	K		CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS	PLUG AND ABANDON		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND			
OTHER:			OTHER:				
 Describe proposed or completed starting any proposed work). SI recompilation. 				ellbore diagrar	n of proposed cor	mpletion or	
BTA Oil Producers plans to P&.	A this well as follows:				2525262 2525262 2525262	728 <i>293</i> 03	
1. Spot 50 sx cmt plug @ 8700-8600' – tag plug with wireline.							
2. Cut and pull 5-1/2" casing @ est 6000' (top cmt @ 6032'; top scab liner @ 7200').							
3. Spot 50 sx cmt plug @ 6050-5950" (5-1/2" stub) - Tag. 4. Spot 65 sx @ 3775-3675" (8-5/8" shoe) - Tag.							
4. Spot 65 sx @ 3775-3675' (8-5/8" shoe) - Tag. 5. Spot 50 sx @ 2500-2400' (Yates). 6. Cut and pull 8-5/8" casing. Est top of cmt @ 1100'. 7. Spot 125 sx @ 450-350' (13-3/8" shoe) - Tag. 8. Spot 10 sx @ surface. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF							
6. Cut and pull 8-5/8" casing.	Est top of cmt @ 1100'.				10	- 8V	
7. Spot 125 sx @ 450-350' (13	3-3/8" shoe) - Tag.		MMISSION MUST		24 St 51 ELZI	rrorg	
8. Spot 10 sx @ surface.9. Install dry hole marker.			PRIOR TO THE ING OPERATIONS		OF 350		
7. Instan dry note marker.			APPROVED.	ON THE C.	103		
I hereby certify that the information	above is true and complete	e to the be	est of my knowledge	e and belief.			
SIGNATURE TO SIGNATURE	MACOP 1	TITLE	Regulatory Admir	nistrator	DATE_ <u>09/2</u>	24/2003	
Type or print name Pam Inskeep				Т	elephone No. (43	32) 682-3753	
(This space for State use)		oci	Diegnisse -				
APPPROVED BY Law 1	المناززان	ייייני די	DISTRICT SUPERVI	SOR/BENIER	Alta is a mana limm	SEP 2 5 2003	
Conditions of approval, if any:	1. Ware	TTLE		- SEINER	HL MANAGER		