

Submit 3 Copies To Appropriate District  
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-32597-00-00
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3406-1

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Water Injection <input type="checkbox"/>	7. Lease Name or Unit Agreement Name:  Central EK Queen Unit
2. Name of Operator Seely Oil Company	8. Well No. Tract 11, # 2
3. Address of Operator 815 West 10 <sup>th</sup> Street, Fort Worth, Texas 76102	9. Pool name or Wildcat EK - Yates - Seven Rivers - Queen
4. Well Location  Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line  Section <u>17</u> Township <u>18S</u> Range <u>34E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Seely Oil Company proposes to temporarily abandon the referenced well as follows:

1. Lay down Salta lined tbg and pkr.
2. Set CIPB @ 4400' w/ 3 sxs cmt on top of plug.
3. Remove wellhead and install a csg valve.
4. Test csg to 500 psi.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David L. Henderson TITLE Vice President DATE 9/26/03

Type or print name David L. Henderson Telephone No. (817) 332-1377

(This space for State use)

APPROVED BY David W. Wink OC DISTRICT SUPERVISOR/GENERAL MANAGER, TITLE DATE

Conditions of approval, if any

SEP 30 2003