

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <u>30-025-20010</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <u>K 385 - 4</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
PENROC OIL CORPORATION

3. Address of Operator
P.O. Box 2769 Hobbs, NM 88241

4. Well Location
Unit Letter L : 1650 feet from the SOUTH line and 330 feet from the WEST line
Section 35 Township 17 S Range 33 E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4130' DR

7. Lease Name or Unit Agreement Name:
STATE 35

8. Well No. 3

9. Pool name or Wildcat
CORBIN ABO

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well was TA'd by Maynard 8/10/02 as per C-103 8/21/02. POC P'd this as per NMOC approval as per requirement by SWD# 874. NMOC notified & operations witnessed by J. Robinson.

9.15.03 - 9.17.03 RU WSU. PU 2 3/8" N-80 tubing. Tagged @ 4547'. RU ZIA w/ 9.4" gelled brine. Circulated hole. TDH. SDFN due to not proper 4 1/2" jet cutters. 9/16 - Cut 4 1/2" csg @ 4045' - csg not free. Ran Free point. G. Wink O.K'd to cut csg @ 1548'. Cut & LD 50 ft of 4 1/2". TTH w/ tbg & spotted 50 sx. plug @ 4095'. TDH to 1548'. Spotted 50 sx. plug. W.O.C. TTH to tag - Did not tag. Mixed & set 2nd 50 sx. plug. W.O.C. 2 hrs. Tagged plug @ 1504'. Spot 120 sx. 399' to surface. RD-MO. Cut off well head, installed dry hole marker. Cleanup location 9/25/03.

Approved as to plugging of the Well Bore
ability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Operation Sup. DATE 9.26.03

Type or print name TRACY HEADSTREAM
(This space for State use)

Telephone No. (505) 492-1236

APPROVED BY [Signature]
Conditions of approval, if any

OC DISTRICT SUPERVISOR/GENERAL MANAGER
TITLE [Signature]

DATE OCT 02 2003