Form 3160-5 (August 1999)

N.M. Oil Cons. Division

1625 N. French Dr. UNITED STATES DEPARTMENT OF THE INTERIOR HODDS, NM 88240 BUREAU OF LAND MANAGEMENT HODDS, NM 88240

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No. NM-18848

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Do not use this form for proposals.	6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE - Other instructions on reverse side	7. If Unit or CA/Agreement, Name and/or No.
Type of Well	8. Well Name and No.
Oil Well Gas Well Other	SDE "19" Federal #3
Name of Operator	9. API Well No.
Chevron USA Inc 3b. Phone No. (include area code)	30-025-32908
a. Address 15 Smith Rd, Midland, TX, 79705 (432) 687-7153	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)	Triste Draw Delaware, Wes
	11. County or Parish, State
Unit Letter N, 330' FSL, 2310 FWL	Lea, NM
Section 19, Township 23-S, Range 32-E 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	
TYPE OF ACTION	
TYPE OF SUBMISSION	(Resume) Water Shut-Off
Acidize Deepen Production (Star	Well Integrity
Notice of Intent After Casing	Other
Subsequent Report	
Change rialis Water Disposal	
Final Abandonment Notice Convert to Injection Plug Back Water Disposal 3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of a lif the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and to lif the proposal is to deepen directionally be performed or provide the Bond No. on file with BLM/BIA. Requ	and work and approximate duration thereof.
Attach the Bond under Which in the Work operations. If the operation results in a multiple completion or recompletion following completion of the involved operations. If the operation results in a multiple completion or recompletion following completion of the involved operations. If the operation after all requirements, including reclassing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclassing that the site is ready for final inspection.) 1. Notify BLM 24 hrs prior to MI & RU. 2. RIH Tag TOC on CICR @ +-5230, spot 25sx plug 5 WOC Tag.	230-5100 (Delaware)
3. Displace hole w/MLF, 9.5# brine w/25# gel P/BB	WOC Tag.
4. Spot 30sx plug 4650-4400, (8 5/8 shoe, Ramsey)	
5. Cut 5 1/2" csg @ 4050, L/D csg. 6. Spot 50sx plug 4100-3900, (STUB) WOC Tag.	APPROVED
0 Cnot 50cv 51ug 1100-900 (T-Salt) WOC 149.	255 2 2 222
9. Spot 110sx plug 610-200 (11 3/4 shoe) WOC Tag.	SEP 2 9 2003
10. 10sx surf, install dry hole marker.	
10. 1001 0411, 200	GARY GOURLEY
	PETROLEUM ENGINEER
14. I hereby certify that the foregoing is true and correct	
Name (Printed Typed) Title HES SA	ecialist
G.R. Dleason Date 9/22/2	ecialist .003
Signature / Company THIS SPACE FOR FEDERAL OR STATE OFFICE US	TO THE SECTION OF A SECTION AND ASSESSMENT OF A SECTION O
IND SPACE FOR FEBRUARY IN THE SPACE FEBRUARY IN TH	
Approved by	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	access of the United

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PLUGGING & ABANDONMENT WORKSHEET

