Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Re	esources March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-05405
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIV	TSION 5. Indicate Type of Lease
District III 1220 South St. Francis I	Or. STATE FEE 7
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	o. State on & Gas Bease 110.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS 29 3	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERS OF PLUG BY DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10)) FOR SUC	Lovington Paddock Unit
PROPOSALS.)	0 77/ 1137 1
1. Type of Well:	8. Well Number
Oil Well Gas Well Other Silved 2. Name of Operator	67
	9. OGRID Number
2. Name of Operator Chevron Mid Continent L.P. Chevron Mid Continent L.P.	241333
3. Address of Operator 11111 S. Wilcrest, Houton, Tx 77099 4. Well Location	10. Pool name or Wildcat Lovington Paddock
11111 S. Wilcrest, Houton, Tx 77099	Lovington Paddock
4. Well Location	
L 2240 Courth	660 Wort
Unit Letter L: 2310 feet from the South	line and 660 feet from the West line
6	27 5 27 50 60 60
Section 6 Township 17-S Range	37-E NMPM Lea County
11. Elevation (Show whether DR, RKB)	RI, GR, etc.)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144	must be attached)
Pit Location: UL L Sect 6 Twp 17S Rng 37E Pit type Steel Depth to	
THE LOCATION OF LESSEE O TWP 170 King O'LE PILTYPE OLGEN DEPTH TO	Groundwater 10 Distance from nearest tresh water wen
Distance from nearest surface water Below-grade Tank Location UL	Sect;
2310 feet from the South line and 660 feet from the West line	\mathcal{L}_{i}
· · · · · · · · · · · · · · · · · · ·	
12 Check Appropriate Roy to Indicate Nature	of Notice Penart or Other Data
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF INTENTION TO:	of Notice, Report or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	of Notice, Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM	of Notice, Report or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REM TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COM	of Notice, Report or Other Data SUBSEQUENT REPORT OF: MEDIAL WORK □ ALTERING CASING □ MMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT □
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REM TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COM PULL OR ALTER CASING ☐ MULTIPLE ☐ CAS	of Notice, Report or Other Data SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING MENCE DRILLING OPNS. PLUG AND ABANDONMENT SING TEST AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REM TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COM PULL OR ALTER CASING ☐ MULTIPLE ☐ CAS	of Notice, Report or Other Data SUBSEQUENT REPORT OF: MEDIAL WORK □ ALTERING CASING □ MMENCE DRILLING OPNS.□ PLUG AND ABANDONMENT □
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CASING COMPLETION CASING CEN	SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING MENCE DRILLING OPNS. PLUG AND ABANDONMENT SING TEST AND MENT JOB
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION OTHER:	SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ABANDONMENT SING TEST AND ABANDONMENT MENT JOB MER:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CHANGE PLANS COM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine)	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ABANDONMENT SING TEST AND ABANDONMENT MENT JOB MER: Cont details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE COMPLETION CEN OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Completed operations.	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ABANDONMENT SING TEST AND ABANDONMENT MENT JOB MER: Cont details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Corporations.	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING MENCE DRILLING OPNS. PLUG AND ABANDONMENT SING TEST AND MENT JOB MER: Potential dates, including estimated date in pletions: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ABANDONMENT SING TEST AND ABANDONMENT MENT JOB MER: Cont details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CASING COMPLETION OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Corror recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ABANDONMENT SING TEST AND MENT JOB MER: Ment details, and give pertinent dates, including estimated date inpletions: Attach wellbore diagram of proposed completion Mont 20 sx class c cmt 155' surf 6/22/07 stall dry Hole Marker 6/22/07
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE COMPLETION CEN OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING C
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CASING PULL OR ALTER CASING SCHOOL CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Corror recompletion. 1. Notified ocd on P & A intent 8. Sp 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07	SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT SING TEST AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMPLETION COMPULL OR ALTER CASING MULTIPLE COMPLETION CENTER OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Completion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING MEDIAL WORK ALTERING CASING MEDIAL WORK ABANDONMENT SING TEST AND MENT JOB MENT JOB MER: MEDIAL WORK ABANDONMENT SING TEST AND MENT JOB MENT JOB MER: MEDIAL WORK ABANDONMENT SING TEST AND MENT JOB MENT JOB MENT JOB MER: MEDIAL WORK ABANDONMENT SING TEST AND MENT JOB MENT J
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMPLETION COMPLETION COMPLETION CENTER OTHER: OTHER: OTHER CASING MULTIPLE COMPLETION CENTER 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Completion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of the complete to the complete to the best of the complete to the	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ALTERING CA
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMPLETION COMPULL OR ALTER CASING MULTIPLE COMPLETION CENTER OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Completion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ALTERING CA
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE COMPLETION CEN OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a gen	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @ 2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE	SUBSEQUENT REPORT OF: MEDIAL WORK ALTERING CASING ALTERING CA
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Corror recompletion. 1. Notified ocd on P & A intent 2. Set 5 1/2 CIBP @ 6100 6/19/07 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE MA	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @ 2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 4730 , Tag @ 4520 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt fo/20/07 Tag toc @ 2790 6/21/07 6. Perf @ 2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE TITLE Type or print name Type or print name E-mail address:	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Corror recompletion. 1. Notified ocd on P & A intent 2. Set 5 1/2 CIBP @ 6100 6/19/07 3. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx of class c cmt @ 6100-5875 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE MA	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 12. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 2. Set 5 1/2 CIBP @ 6100 6/19/07 19. Ins. 3. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt 6/20/07 Tag toc @ 2790 6/21/07 6. Perf @ 2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines a gen SIGNATURE TITLE FAG Type or print name E-mail address:	SUBSEQUENT REPORT OF: MEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REM TEMPORARILY ABANDON CHANGE PLANS COM PULL OR ALTER CASING MULTIPLE CAS COMPLETION CEM OTHER: OTH 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Cor or recompletion. 1. Notified ocd on P & A intent 8. Sp. 2. Set 5 1/2 CIBP @ 6100 6/19/07 9. Ins. 3. Spot 25 sx of class c cmt @ 4730 , Tag @ 4520 6/20/07 4. Spot 25 sx class c cmt @ 4730 , Tag @ 4520 6/20/07 5. Perf @ 3340 squeezed 115 sx class c cmt fo/20/07 Tag toc @ 2790 6/21/07 6. Perf @ 2160 Squeezed 125 sx class c cmt tag @ 1705 6/21/07 7. Perf @ 325 Sqeezed 200 sx class c cmt 6/21/07 tag @ 155 6/22/07 I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE TITLE Type or print name Type or print name E-mail address:	SUBSEQUENT REPORT OF: MEDIAL WORK