Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

•	OIL CONICEDIA TI	AL DIVITATA	T			
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	Santa Fe, NM 87505		WELL API NO. 30-025-23389			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type		33 84	
DISTRICT III				STATE L] FEE	
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Ga	s Lease No.		
	CES AND REPORTS ON WE					
	VOIR. USE "APPLICATION FOR PE		7. Lease Name of	r Unit Agreeme	ent Name	
1. Type of Well:	01) FOR SUCH PROPOSALS.)		STATE H			
OIL GAS WELL WELL	OTHER					
2. Name of Operator BRECK OPERATING CORP.			8. Well No.			
3. Address of Operator		-	9. Pool name or V	Wildcat		
4. Well Location	MITTERS PROPERTY.					
Unit LetterB: 330	Feet From The NORTH	Line and16	50 Feet Fron	n The E	AST	Line
Section 17	Township 22 S Rai	nge 36 E	NMPM	LEA	Co	ounty
	10. Elevation (Show wheth					
11. Check App	propriate Box to Indicate	e Nature of Not	ice, Report, c	or Other D) ata	<u> </u>
NOTICE OF INTENTION TO:			SEQUENT F			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CA	ASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING		PLUG AND AE		NT X
PULL OR ALTER CASING		CASING TEST AND C		, 200 / 110 / 12		•••
OTHER:		OTHER:				
12. Describe Proposed or Completed Ope	uration (Clearly state all portinent de	<u> </u>	datas insludina as	timeted data a	. 6 at a mt i m = = = =	
work) SEE RULE 1103.	rations creating state all pertinent de	tans, and give periment	uates, including es	stimated date o	n starting an	у ргороз
9-11-03 SPOT 50 SKS @ 3600) SET CIDD W/ SE SVS ON TO	ND.				
0 10 00 CDOT OF CIVE O COOK) 251 CIDE M/ 52 2V2 ON 10	JP				
	0 W.O.C. & TAG @ 2630		TAC @ 1206			
9-12-03 SPOT 25 SKS @ 2890 9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3) W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE	25 SKS W.O.C. &	TAG @ 1206			
9-15-03 PERF & SQUEEZE 25) W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE	25 SKS W.O.C. &	TAG @ 1206	<i>Q</i> ₂),	\$990 ***********************************	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3) W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE	25 SKS W.O.C. &	TAG @ 1206	Q3),	\$900 \$904	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE	0 W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @	25 SKS W.O.C. & 218'		Q3).	\$900 \$900 \$900 \$900 \$900	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved a Liability und	25 SKS W.O.C. & 218' s to plugging of the der bond is retained	Well Bore.	Q3),	\$400 \$400 \$400 \$400 \$400 \$400 \$400 \$400	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved a Liability und	25 SKS W.O.C. & 218'	Well Bore.	93) 2007 2017 - 12	\$9000 \$9004	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved a Liability und	25 SKS W.O.C. & 218' s to plugging of the der bond is retained	Well Bore.	O3.	\$900 \$1904	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved a Liability und surface rest	25 SKS W.O.C. & 218' s to plugging of the der bond is retained oration is complete	Well Bore.	Q3.	\$900 9904	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE CIRC MUD INSTALL P & A MARKER	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved at Liability und surface resto	25 SKS W.O.C. & 218' s to plugging of the der bond is retained oration is complete	Well Bore.	Q3),	9-17-03	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE CIRC MUD INSTALL P & A MARKER	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved at Liability und surface restored and complete to the best of my knowled	25 SKS W.O.C. & 218' s to plugging of the der bond is retained oration is complete edge and belief. E CEMENTER	Well Bore. I until d.	TELEPHONE NO.	9-17-03	
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE CIRC MUD INSTALL P & A MARKER	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved at Liability und surface restored and complete to the best of my knowled	25 SKS W.O.C. & 218' s to plugging of the der bond is retained oration is complete edge and belief. E CEMENTER	Well Bore. I until d.	TELEPHONE NO.		
9-15-03 PERF & SQUEEZE 25 9-16-03 PERF & SQUEEZE @ 3 SPOT 10 SKS 60- SURFACE CIRC MUD INSTALL P & A MARKER I hereby certify that the information above is true. SIGNATURE TYPE OR PRINT NAME JEFF KESTER	O W.O.C. & TAG @ 2630 SKS @ 1440 NO TAG SQUEEZE 380'80 SKS W.O.C. & TAG @ Approved at Liability und surface restored and complete to the best of my knowled	25 SKS W.O.C. & 218' s to plugging of the der bond is retained oration is complete	Well Bore. I until d.	TELEPHONE NO.		032