Submit 3 Copies To Appropriate District State of N	New Mexico		Form C-103
Office District IEnergy, Minerals and Natural ResourcesDistrict I1625 N French Dr., Hobbs NM:87240District II0IL CONSERVATION DIVISION1301 W Grand Ave. Artesia NM 882101220 South St. Francis Dr.District III1220 South St. Francis Dr.1000 Rio Brazos Rd. Zztec, NM87410Santa Fe, NM 87505			May 27, 2004
		WELL API NO.	0
		<u>30-025-2276</u> 5. Indicate Type of Leas	
		STATE X FEE	
		6. State Oil & Gas Lease No.	
1220 S St. Francis Dr , Santa Fe, NM 87505		6. State Oli & Gas Leas	e No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit	Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Vacuum Abo Un	
PROPOSALS.)			
1. Type of Well:		8. Well Number	
Oil Well Gas Well Other Injection		207	
2. Name of Operator	JUN 29 2007	9. OGRID Number	
XTO Energy, Inc.	OCD-ARTESIA	005380 10. Pool name or Wildc	-4
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701		Vacuum; Abo, North	at
4. Well Location		j vacuum, Abo, Not <u>ch</u>	
	No other states a	001 0 0 0	Fact u
Unit Letter <u>H</u> : <u>2121</u> feet from the	line and	teet from the	Last line
Section 24 Township	17S Range 34E	NMPM Co	unty Lea
	whether DR, RKB, RT, GR, e		
	· · · · · · · · · · · · · · · · · · ·		<u> </u>
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from net	arest fresh water well Di	stance from nearest surface wa	ter
Pit Liner Thickness:      mil       Below-Grade Tank: Volumebbls; Construction Material			
PERFORM REMEDIAL WORK CHANGE PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALETER CASING MULTIPLE COMPLETION OTHER:	N  REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB		TERING CASING
13. Describe proposed or completed operations. (Clearly sta			
of starting any proposed work). SEE RULE 1103. For or recompletion.			
5/1/07 RU PU. RIH w/1.87" F plug & WL. Hung 10# brine dwn TCA.	up @ 25'. Pmpd 11 bbls (	of 10# brine dwn tbg.	Pmpd 8 bbls of
5/2/07 Pmpd 27 bbls of 10# brine wtr down tb seal assbly.	g. NU BOP. POOH LD w/27	1 jts of 2-3/8" N80 Bu	ittress tbg &
5/4/07 Pmpd 60 bbls of 10# brine dwn TCA. PU IPC tbg. (Cont'd. on Next Page.)	RIH w/seal assbly & 220	0 jts of 2-3/8" 4.6#,	EUE, 8rd, J-55
I hereby certify that the information above is true and complete	e to the best of my knowledg	e and belief. I further certify	that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD	guidelines 🔲 , a general permit	or an (attached) alternative	e OCD-approved plan
SIGNATURE KING Ward		ry Analyst DAT	E06/27/07
Type or print name Kristy Ward			No. 432-620-6740
For State Use Only	HAR WELL - COLLECTION	TVE II/STAFF MANAGER	
APPROVED BY Hary W. Wink	DETTED REPRESENTATI	DATE	
Conditions of Approval, if any:			

North Vacuum Abo Unit #207 Repr. Tbg. And/or Pkr. Leak & RWTI Page 2 Cont'd.

- 5/5/07 Pmpd 30 bbls of 10# brine dwn TCA. PU & RIH w/40 jts of 2-3/8"
  4.6#, EUE, 8rd, J-55 IPC tbg, 2-3/8" 4.6#, EUE, 8rd, J-55, 10', 8',
  6', 4' IPC tbg subs, 1 jt of 2-3/8" 4.6#, EUE, 8rd, J-55 IPC tbg &
  2 3/8" 8rd x 2 3/8" buttress chg over. Circ 100 bbls of pkr fluid. ND BOP. NU WH.
- 5/8/07 Pmpd 16 bbls of pkr fluid dwn TCA. Pmpd 15 bbls of 10# brine wtr dwn tbg. RIH w/1.78 F plug & WL. Set plug in seating nipple. Pmpd 28 bbls of 10# brine wtr dwn tbg.
- 5/9/07 Pmpd 22 bbls of 10# brine wtr dwn tbg. ND WH. NU BOP. POOH w/2-3/8" IPC tbg & seal assbly.
- 5/11/07 RIH w/seal assbly & 260 jts of 2-3/8" 4.6#, EUE, 8rd, J-55 IPC tbg, 2-3/8" 4.6#, EUE, 8rd, J-55, 10', 8', 6', 4' IPC tbg subs, 1 jt of 2-3/8" 4.6#, EUE, 8rd, j-55 IPC tbg & 2-3/8" 8rd x 2-3/8" buttress chg over. Pmpd 30 bbls of 10# brine dwn tbg. Circ 100 bbls of pkr fluid. Set seal assbly.
- 5/12/07 Pmpd 30 bbls of 10# brine dwn tbg. ND COP. NU WH. RDMO PU. RWTI.

**MIT Chart Attached.** 

1



÷

5/11/07 Emby Carl Child monres

.

. `

.