Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Revised June 10, 2003 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II			30 025 03165
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FFF X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Northeast Pearl Queen Unit	
PROPOSALS.)	,		8. Well Number
1. Type of Well: Oil Well X Gas Well Other (Injection)		2	
		0. OCDID Number	
2. Name of Operator  Melrose Operating Company 184860		184860	
3. Address of Operator		10. Pool name or Wildcat 456	
c/o Box 953 Midland, TX 79702		Pearl: Queen of	
4. Well Location			
Hait Letter 11 220 feet from the South line and 1650 feet from the West (line of the line)			
1. Type of Well: Oil Well X Gas Well Other (Injection)  2. Name of Operator Melrose Operating Company 184860  3. Address of Operator c/o Box 953 Midland, TX 79702  4. Well Location Unit Letter M 330 feet from the South line and 1650 feet from the West line satisfies the Section 15 Township 19S Range 35E NMPM Eddy County 2 County 2			
Section 15 Township	p 19S Range 35E	NMPM Edd	9 County & Porting &
11. Elevation (Show whether DR, RKB, RT, GR, etc.): 3763			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12026189			
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
	-		
TEMPORARILY ABANDON		ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE     COMPLETION	CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. 6-1-07: Rigged up and pulled rods & pump.			
6-4-07; RIH w/shoe & ash pipe & tubing. Tagged @ 4830'. Cleaned out to 4843'. Recovered short piece of junk tubing.			
6-5-07: RIH and tagged @ 4343'. Drilled to 4851'. POOH w/ 4 ft. of junk tubing.			
6-6-07: RIH w/bit, cleaned out to 4888', POOH & cleaned out tubing.			
6-7-07: RIH and cleaned out to 4970;, RIH w/ 4 ¾" bit, tagged @ 4958'.			
6-8-07: RIH w/ tubing, tagged @ 4958, milled to 4982'. POOH w/ old SN, Ran back in hole with tubing. 6-12-07: Scanned tubing, RIH w/good tubing, set SN @ 4920'.			
6-13-07: Swabbed. Ran in hole with pump & rods, flushed well.			
6-14-07: RU and swabbed to tank. RIH w/pump & rods, stroked pump. Well test: 3 oil, 120 water and 0 gas.			
Wellput back on production as part of ACO compliance order.			
	<b>F</b>		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Regulatory Agent DATE: 7-13-07			
Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381			
(This space for State use)			
H	11. 12. 12		JUL 1 8 2007
APPPROVED BY Conditions of approval, if any	J. WMC/2_ TITLE_	A 47	VE WATAF MARAPATE JOL 1 5 200.
APPPROVED BY LOUY WITH TITLE  Conditions of approval, if any.  OC FIELD REPRESENTATIVE II/STAFF MANAGETE JUL 18 2007			