Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-005-10573 5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE FEE P
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	24,100	o. Sant on a san san
87505		Z I N
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	CATO SAN ANDRES
PROPOSALS.)	CAHON FOR ERMIT (FORM C 101) FOR GOOT	8. Well Number #74
1. Type of Well: Oil Well	Gas Well Other	
2. Name of Operator		9. OGRID Number
CANO PETROLEUM		10 D 1 Wilder
3. Address of Operator		10. Pool name or Wildcat
801 CHERRY ST SUIT 3200 UN	TT 25 FORT WORTH TX 76102-6882	SAN ANDRES
4. Well Location	110	110
Unit Letter D:	660 feet from the N line and R	660 feet from theline
Section 15	1011101110	0E NMPM County CHAVEZ
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
Pit or Below-grade Tank Application	or Closure 🔲	
Pit type Depth to Groundy	vaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volumebbls;	Construction Material
PR Liner Thickness.		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN	NTENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK X	PLUG AND ABANDON ☐ REMEDIAL W	
TEMPORARILY ABANDON		DRILLING OPNS. P AND A
PULL OR ALTER CASING	D CACINIO/OFM	
PULL OR ALTER CASING L	MOLIN EL COM L	
		_
	☐ OTHER:	
OTHER:	-1-to-d amorations (Clearly state all pertinent details	and give pertinent dates, including estimated date
OTHER:	-1-to-d amorations (Clearly state all pertinent details	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w	-1-to-d amorations (Clearly state all pertinent details	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	-1-to-d amorations (Clearly state all pertinent details	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	Attach wembore diagram of proposed complement
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	on Solution we mode that the proposed completion on the proposed completion of the proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 7-16-07 Clean out well bore	pleted operations. (Clearly state all pertinent details, vork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production	on Attach wembore diagram of proposed completion on on on on on on on on on
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 7-16-07 Clean out well bore	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production or the second state of the best of my knowledge.	Attach wembore diagram of proposed completion. On On On On On On On On On
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 7-16-07 Clean out well bore	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production or the second state of the best of my knowledge.	Attach wembore diagram of proposed completion. On On On On On On On On On
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 7-16-07 Clean out well bore	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production with air foam unit check csg return well to production above is true and complete to the best of my known or closed according to NMOCD guidelines , a general perm	The dege and belief. I further certify that any pit or belowit \square or an (attached) alternative OCD-approved plan \square .
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 7-16-07 Clean out well bore	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production or the second state of the best of my knowledge.	The dege and belief. I further certify that any pit or belowit \square or an (attached) alternative OCD-approved plan \square .
OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 7-16-07 Clean out well bore I hereby certify that the information grade tank has been/will be constructed. SIGNATURE	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production with air foam unit check csg return well to production above is true and complete to the best of my known or closed according to NMOCD guidelines , a general perm	redge and belief. I further certify that any pit or below- it DATE
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 7-16-07 Clean out well bore I hereby certify that the information grade tank has been/will be constructed SIGNATURE Type or print name GENE BRO	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production above is true and complete to the best of my knowledge according to NMOCD guidelines , a general permonent of the production of the producti	redge and belief. I further certify that any pit or below- it DATE 7-16-07 DATE 7-16-07
OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 7-16-07 Clean out well bore I hereby certify that the information grade tank has been/will be constructed SIGNATURE	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production above is true and complete to the best of my knowledge according to NMOCD guidelines , a general permonent of the production of the producti	redge and belief. I further certify that any pit or below- it DATE
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 7-16-07 Clean out well bore I hereby certify that the information grade tank has been/will be constructed. SIGNATURE Type or print name GENE BROEFOR State Use Only	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production above is true and complete to the best of my known or closed according to NMOCD guidelines , a general permonent of the production for the	redge and belief. I further certify that any pit or below- it DATE 7-16-07 DATE 7-16-07
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 7-16-07 Clean out well bore I hereby certify that the information grade tank has been/will be constructed SIGNATURE Type or print name GENE BRO	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: with air foam unit check csg return well to production above is true and complete to the best of my knowledge according to NMOCD guidelines , a general permonent of the production of the producti	redge and belief. I further certify that any pit or below- it DATE 7-16-07 DATE 7-16-07