

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-28607

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-732

7. Lease Name or Unit Agreement Name
N.M. St. D.L.

8. Well Number
#2

9. OGRID Number
12281

10. Pool name or Wildcat
CRUZ DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator PRONGHORN MANAGEMENT CORPORATION

3. Address of Operator P. O. BOX 1772 HOBBS, NM 88241

4. Well Location
Unit Letter 0 : 660 feet from the South line and 1980 feet from the EAST line
Section 18 Township 23-S Range 33E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OGD approved plan ☐.

SIGNATURE [Signature] TITLE President DATE 7/18/07

Type or print name: E-mail address: Telephone No.

(This space for State use)

APPROVED BY [Signature] TITLE DATE
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER 23 2007

1. Move in and rig up. POOH with rods and pump.
2. Swab well. Check for production and fluid level.
3. Install B.O.P. POOH with tubing.
4. Perforate additional pay in Ramsey Sand.
5. TIH with frac tubing and packer.
6. Rig up BJ. Frac well.
7. Flow and swab test well.
8. Put well on production.
9. Clean location. Rig down. Move out.