Submit 3 Copies To Appropriate District Office	State of New Energy, Minerals and N		Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, winicials and r	vaturar Resources	WELL API NO.
District II 1301 W. Grand Avc., Artesia, NM 88210			30-025-28610 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. I Santa Fe, NM		STATE E FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Salita Fe, Niv	1 67303	6. State Oil & Gas Lease No. V-732
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			N.M. ST. D.L.
1. Type of Well: Oil Well X Gas Well Other			8. Well Number 5
2. Name of Operator PRONGHORN MANAGEMENT CORPORATION		9. OGRID Number 122811	
3. Address of Operator P. O. BOX 1772 HOBBS, NM 88241		10. Pool name or Wildcat LEA	
4. Well Location			
Unit Letter J: 1980 feet from the South line and 1650' feet from the East line			
Section 18	Township 23S		NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface waterBelow-grade Tank Location ULSectTwpRng;			
feet from theline andfeet from theline			
,			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF I	NTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	C □ ALTERING CASING □
TEMPORARILY ABANDON		COMMENCE DRII	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB	_
OTHER:		OTHER:	618910111213 D
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.	olk). SEE ROLE 1103. FOR MUI	tiple Completions: Aft	ach wellbore diagram of proposed completion
			17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18
			130
			10
			11 1374 565 623
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE MMULL	TITLE	President	DATE 7/18/07
Type or print name	E-mail	address:	Telephone No.
This space for State use)			,
APPPROVED BY LOWW	WWD TIFE	aelo representat	DATE_
Conditions of approval, if any:			TVE II/STAFF MAN JUE 2 3 2007

- 1. Move in and rig up. POOH with rods and pump.
- 2. Swab well. Check for production and fluid level.
- 3. Install B.O.P. POOH with tubing.
- 4. Perforate additional pay in Ramsey Sand.
- 5. TIH with frac tubing and packer.
- 6. Rig up BJ. Frac well.
- 7. Flow and swab test well.
- 8. Put well on production.
- 9. Clean location. Rig down. Move out.