


UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS



SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		7. If Unit of CA/Agreement, Name and/or No
2 Name of Operator CHESAPEAKE OPERATING, INC. ATTN: LINDA GOOD		8. Well Name and No. DINWIDDIE 23 FEDERAL 1
3a Address P O BOX 18496 OKLAHOMA CITY, OK 73154-0496	3b Phone No (include area code) 405-767-4275	9. API Well No. 30-025-38242
4. Location of Well (Footage, Sec, T., R., M, or Survey Description) 1400 FNL & 660 FEL, SENE, SECTION 23, T25S, R35E		10. Field and Pool or Exploratory Area WILDCAT
		11 Country or Parish, State LEA COUNTY, NEW MEXICO

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input checked="" type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other SET 2 OIL TANKS
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	


13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

CHESAPEAKE OPERATING, INC. IS SETTING 2 ADDITIONAL 300 BARREL OIL TANKS FOR THIS WELL. THESE TANKS ARE NECESSARE DUE TO THE OIL PRODUCTION FROM THIS WELL. THE BERM WAS.BUILT LARGE ENOUGH TO ACCOMODATE THESE TWO ADDITIONAL OIL TANKS.

SHARON DRIES OF CHESAPEAKE SPOKE WITH JERRY BLAKLEY, PETROLEUM ENGINEER TECHNICIAN ON JULY 12, AND SHE RECEIVED VERBAL PERMISSION TO SET THESE TANKS.

BLM NATIONWIDE BOND NM2634

(CHK PN 612528)



14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed) SHARON E. DRIES (405-879-7985)	Title SENIOR REGULATORY COMPLIANCE SPECIALIST
Signature <i>Sharon E. Dries</i>	Date 07/12/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

SWW