

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03836
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other INJECTOR ☐
2. Name of Operator CHEVRON MIDCONTINENT, L.P.
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705
4. Well Location
Unit Letter D 660 feet from the NORTH line and 660 feet from the WEST line
Section 1 Township 17-S Range 36-E NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
Pit or Below-grade Tank Application ☐ or Closure ☐
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: REPLACE CSG TOP JOINT

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-06-07: MIRU. 7-09-07: PMP 20 BBLS 14.5# MUD DN TBG. WELL ON VAC. TIH W/TBG PLUG & CCL. TAG UP @ 4412. PULL UP TO 4384. SET TBG PLUG. 7-10-07: TIH W/PERF GUNS. SHOOT 4 HOLES IN 2 3/8" TBG @ 4353. JET CUT TBG @ 4373. TIH W/SPEAR. PULL. REM SLIPS. TBG NOT FREE. WORK TBG FREE. PU RBP SET @ 4331. PULL PKR UP & TEST RBP. 7-11-07: CIRC OUT 14.5# MUD. RETEST RBP @ 4331. REL PKR @ 4323. TIH W/RBP, 2 3/8" TBG TO 327. SPOT 2 SX SAND ON RBP. 7-12-07: TEST 5 1/2" CSG TO 500# - 15 MINS. LOST 5# GOOD. WASH SAND OFF RBP @ 327. LATCH ONTO RBP & REL. TEST 5 1/2" CSG TO 520#. GOOD. TIH W/RETR HEAD & 2 7/8" WS TO 330. 7-13-07: LATCH ON BP @ 4331. REL. REV CIRC 95 BBLS. TIH W/2 7/8" TBG OPEN ENDED. EOT @ 2531. 7-16-07: TIH W/BHA W/140 JTS 2 7/8" WS TO 4538. PUMP 7 BBLS 14.5# MUD DN TBG. KILL TBG. TIH W/WS TO TAG TOF @ 4667. PUSH FISH DN TO 4890. BTM OF PKR @ 4470. 100' FILL BTM @ 5070. 7-17-07: CORRECTION TOP OF FISH (4870') PU SPEAR, GRAPPLE, JARS, WS TO 4870. LATCH ONTO FISH & JAR LOOSE. EST BTM FISH @ 2736'. 7-18-07: PU SHOE, BMPR SUB, JARS, WS TO 4943. BROKE CIRC. DRILL 4943-5010. HANG UP ON SHOE @ 5005'. 7-19-07: PU RBP, PKR, SN, WS TO 4446. SET RBP @ 4446. PULL PKR TO 4412. REL PKR. LATCH ONTO RBP. PU NEW PKR & 80 JTS 2 3/8" INJ TBG TO 2585. 7-20-07: SPACE OUT. SET PKR @ 4448'. CIRC PKR FLUID. CHART & TEST TO 540#. LOST 10# IN 33 MINS. GOOD. (ORIGINAL CHART & COPY OF CHART ATTACHED). PUMP OUT PUMP OUT PLUG. FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Denise Pinkerton TITLE REGULATORY SPECIALIST DATE 7-24-2007

Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.com Telephone No. 432-687-7375

For State Use Only

APPROVED BY: Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 12 2007
Conditions of Approval (if any):

dm

