

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-07192
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Saber Resources LLC		6. State Oil & Gas Lease No.
3. Address of Operator 400 W Illinois, Suite 950, Midland, Texas 79701		7. Lease Name or Unit Agreement Name Rosa Shults
4. Well Location Unit Letter <u>N</u> <u>330</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>18</u> Township <u>12S</u> Range <u>38E</u> NMPM Lea County		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3873' GR</u>		9. OGRID Number 236378
Pit or Below-grade Tank Application ☐ or Closure ☐		10. Pool name or Wildcat
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mll Below-Grade Tank: Volume _____ bbls Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Re-enter Well ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/24/07 - 7/14/07

MI RU PU, NU BOP. RIH and tag 7" casing at 4567'. Mill and dress casing to 4578'. Run 115 jnts of 7" casing and tie 7" back together @ 4578' with lead patch seal. Test casing to 500 psi, clean out 7" casing to top of liner @ 11887'. Clean out inside liner to PBTD of 11950'. Run production equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

Douglas Keathley

TITLE

VP- Operations

DATE

7/23/07

Type or print name: Douglas Keathley

E-mail address: doug@saberresources.com

Telephone No. 432-685-0169

For State Use Only

APPROVED BY:

Chris Williams

OC DISTRICT SUPERVISOR/GENERAL MANAGER

TITLE

DATE

JUL 24 2007

Conditions of Approval (if any):