Submit 3 Copies To Appropriate District Office	State of New M	Form C-103				
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and Nat	WELL API NO.				
District II 1301 W. Grand Ave., Artesia NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		30-025-29586 5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd , Aztec, NM 87410			STATE FEE			
District IV 1220 S. St. Francis Dr., Santayle, NM 8750			6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lanca Nam	an and I I with A amounts	mt Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Eunice Monument South Unit			
1. Type of Well:		8. Well Number				
Oil Well Gas Well	Other Injection	328 WIW				
2. Name of Operator		9. OGRID Number				
XTO Energy, Inc. 3. Address of Operator		005380 10. Pool name or Wildcat				
-	00 N. Loraine, Ste. 800 Midland, TX 79701			Eunice Monument; Grayburg-San Andres		
4. Well Location						
Unit Letter J:	2080 feet from the So	outh line and	1880' fee	et from the Eas	st line	
Section 7	Township 21S	Range 36E	NMPM	County	Lea	
,	11. Elevation (Show whether	r DR, RKB, RT, GR, et	c.)			
Pit or Below-grade Tank Application	or Closuro					
		sch water well Die	stance from neares	t surface water		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material						
		,				
	Appropriate Box to Indicat	· ·				
NOTICE OF INT			SEQUENT	REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK] ALTERING	CASING	
TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRILL	NG OPNS.	PLUG AND ABANDON		
PULL OR ALTER CASING L	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB				
OTHER:		OTHER:				
13. Describe proposed or complete	d operations. (Clearly state all p		e nertinent dates	s including estimate	ed date	
	SEE RULE 1103. For Multip					
•		• • • • •				
	inj packer & POOH w/pack					
 Scanalog tbg while POOH, laying down the bad joints. MIRU wireline company. RIH w/wireline and CIBP to +/-3,700' and set CIBP. RDMO. 						
4. RIH w/inj string to test casing and CIBP.						
5. MIRU pump company. Pump fresh water and pressure test casing to 500#. Perform MIT. If test is o.k.,						
	fluid. Circulate. POOH.					
6. NDBOP. NUWH. RDMOPU.						
I hereby certify that the information a	hove is true and complete to the	hest of my knowledge	and balief If.	with an agent of the state of		
grade tank has been/will be constructed or	closed according to NMOCD guideling	ies , a general permit	or an (attached	tiner certify that any j	pit or below- proved plan	
SIGNATURE Fristy h			ry Analyst		7/27/07	
Type or print name Kristy Ward	, , , , , _E .	-mail address: kr		Telephone No. 432	-620-6740	
For State Use Only	1, 1, 1, 1	TABLO REPRESENTAT	ive ivstait a	ANNACE		
APPROVED BY — Jaw	W.W.MA	fTLE		dateKU3	1 6 2007	
Conditions of Approval, if any:				_		



WELL DATA SHEET

