
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO DISTRICT I 1220 South St. Francis Dr. 1625 N French Dr , Hobbs, NM 88240 30-025-07594 Santa Fe, NM 87505 5 Indicate Type of Lease DISTRICT II 1301 W Grand Ave, Artesia, NM 88210 STATE FEE X DISTRICT III 6 State Oil & Gas Lease No 1000 Rio Brazos Rd, Aztec, NM 87410 7 Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Unit DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals) Section 3 8 Well No 58 Oil Well Gas Well Other Temporarily Abandoned 2 Name of Operator 9 OGRID No 157984 Occidental Permian Ltd. 10 Pool name or Wildcat 3 Address of Operator Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4 Well Location Unit Letter Feet From The Feet From The Line 660 South 1980 West 19-S NMPM Section Township Range County 38-E Lea 11 Elevation (Show whether DF, RKB, RT GR, etc.) 3608' DF Pit or Below-grade Tank Application or Closure Depth of Ground Water Distance from nearest fresh water well _ Distance from nearest surface water Pit Liner Thickness Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS **PLUG & ABANDONMENT** PULL OR ALTER CASING CASING TEST AND CEMENT JOB Multiple Completion OTHER OTHER. MIT test/HCP/TA status request 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. ND wellhead/NU BOP. 2. Unset & POOH w/5-1/2" packer. 3. RIH w/5-1/2" CIBP set @3900'. Pressure test CIBP. Held OK. 4 POOH w/tubing & lay down. 5. RU wire line & dump 20 ft of cement on top of CIBP. Top of cement @3880'. RD wire line. 6. ND BOP/NU wellhead Test casing to 720# for 30 minutes and chart for the NMOCD. 8. RDPU & RU. Clean location. 9. Well is TA'd. This Approval of Temporary Abandonment Expires RUPU 07/31/07 RDPU 08/02/2007 I hereby certify that the information above is true and complete to the best of my knowledge and belief. If urther certify that any pit or below-grade tank-has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan **SIGNATURE** Administrative Associate DATE 08/09/2007 TYPE OR PRINT NAME TELEPHONE NO Mendy Johnson E-mail address: mendy johnson@oxy.com 806-592-6280 For State Use Only OC PENTILEPESSINATION APPROVED BY CONDITIONS OF APPROVAL ANY



. 将 数 3

Oxy Herman South Hobbs Un, 4

alang belan Paganggapa

स्तर प्रकार प्रकार क्षेत्रकार स्टब्स् स्टान्स्य प्रकार स्वरूप क्षेत्रकारी