Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District.I	Energy, Minerals and Natur	ral Resources-		May 27, 2004
1625 N French Dr , Hobbs, NM 87240 District II			WELL API NO. 30-025-09303	
1301 W Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE ▼ FEE □	
District IV 1220 S. St Francis Dr., Santa Fe, NM 87505	•		6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			7. Lease Name or Unit Agreement Name: STATE A A/C 3 Com A	
1. Type of Well:	Other		8. Well Number	
Oil Well Gas Well 2. Name of Operator	Other		9. OGRID Number	
Petrohawk Operating Co.			194849	
3. Address of Operator		10. Pool name or Wildcat		
1331 Louisian, SUITE 5600 HOUSTON, TEXAS 77002		JAIMAT; TAN, YATES, 7-RVRS (GAS) 79240		
4. Well Location				
Unit Letter G:	1980 feet from the NOF	ETH line and	2310 feet fr	om the <u>EAST</u> line
Section 10		Range 36E	NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3461 'GR				
Pit or Below-grade Tank Application	or Closure			
Pit type <u>n/a</u> Depth to Groundwater <u>149'</u> Distance from nearest fresh water well <u>1000'+</u> Distance from nearest surface water <u>1000'+</u>				
Pit Liner Thickness:n/a mil Below-Grade Tank: Volume500 bbls; Construction Material _Steel (Frac Tanks)				
12. Check A  NOTICE OF INTE  PERFORM REMEDIAL WORK   TEMPORARILY ABANDON   PULL OR ALTER CASING   OTHER:	ppropriate Box to Indicate ENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION		SEQUENT RE	
13. Describe proposed or completed	operations (Clearly state all per	rtinent details, and giv	e pertinent dates, ir	ncliiding estimated date
of starting any proposed work). or recompletion.	SEE RULE 1103. For Multiple	e Completions: Attach	n wellbore diagram	of proposed completion
Please see attached work	order and wellbore diagram	m.		
	BE NOTII	CONSERVATION FIED 24 HOURS IG OF PLUGGIN	PRIOR TO TI	, pro-
I hereby certify that the information ab				
grade tank has been will be constructed or cl	losed according to NMOCD guideline	, a general permit	or an (attached) al	lternative OCD-approved plan
SIGNATURE PLANE (MILE)	TIT E-n	LE Regu nail address:	latory Svaughn@petroha	DATE08/02/07 awk.com
Type or print name Sheila Vaughn	n			ephone No. 832-369-2109
For State Use Only	1, ) Winh			
APPROVED BY Conditions of Approval, if any:	CK TO	TLE LD SUPERMENT Y	The the contract of the second	AUG 1 3 2007



## State A A/C-3 #5 Jalmat Field Lea County, NM

July 31, 2007

## Plug and Abandonment Procedure

- 1. MIRU plugging rig. ND wellhead. NU BOP. TIH with workstring and 4-3/4" bit to ~3,600'. Circ well with 10 ppg gelled brine. POH w/tbg and bit.
- 2. RU wireline and set CIBP at ~3000'.
- 3. TIH w/open ended tubing to CIBP at 3,000'. Mix and spot 300' base of salt cement plug from 3,000' to 2,700' (34 sx of class A).
- 4. Perforate 5-1/2" casing at 1,310'. Mix 200' top of salt cement plug (52 sx class A). Pump through perfs at 1,310' leaving top of cement inside casing at 1,110'. WOC and tag top of plug to verify depth.
- 5. Perforate 5-1/2" casing at 370'. Mix surface plug (96 sx class A). Squeeze through perfs at 370', attempting to circulate cement to surface. Leave top of cement inside casing at surface.
- 6. Cut off wellhead, cap well and install P&A marker.
- 7. Clean location for OCD inspection.

