State of New Mexico Energy, Minerals and Natural Resources Department

1220 South St. Francis Dr.

Santa Fe, NM 87505

FILE IN TRIPLICATE

1625 N French Dr , Hobbs, NM 88240

DISTRICT I

DISTRICT II

.

Form C-103 Revised 5-27-2004 **OIL CONSERVATION DIVISION** WELL API NO 30-25-28334 -5 Indicate Type of Lease

| 1301 W Grand Ave, Artesia, NM 88210  | STATE X FEE  |
|--|--|
| DISTRICT III   | 6 State Oil & Gas Lease No   |
| 1000 Rio Brazos Rd, Aztec, NM 87410  |  |
| SUNDRY NOTICES AND REPORTS ON WELLS  | 7 Lease Name or Unit Agreement Name  |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals )  | مر South Hobbs (G/SA) Unit<br>Section 4  |
| I Type of Well   | 8 Well No 130  |
| Oil Well X Gas Well Other  |  |
| 2 Name of Operator   | 9 OGRID No 157984  |
| Occidental Permian Ltd.  |  |
| 3 Address of Operator  | 10 Pool name or Wildcat Hobbs (G/SA)   |
| HCR 1 Box 90 Denver City, TX 79323   |  |
| 4 Well Location  | <b>*</b>   |
| Unit Letter F 1403 Feet From The North 1403 Feet   | t From The West Line   |
| Section 4 Township 19-S Range 38-E   | NMPM Lea County  |
| 11 Elevation (Show whether DF, RKB, RT GR, etc.)   |  |
| 3616' GL   |  |
| Pit or Below-grade Tank Application or Closure   |  |
|  |  |
| Pit Type Depth of Ground Water Distance from nearest fresh water well  |  |
| Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Mat  | terial   |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report, or C   | Nikou Deta   |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  |  |
|  |  |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   |  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN   | IS PLUG & ABANDONMENT  |
| PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN   | T JOB  |
| OTHER. Clean out/OAP/Acid treat  |  |
|  |  |
| <ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates<br/>proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed c</li> </ol> | and the second se  |
| proposed work) SEE - KOEE 1105. For Multiple Completions. Attach wendore diagram of proposed c   | ompletion or recompletion.   |
| 1. Kill well. POOH w/tubing & ESP equipment.   |  |
| 2 Clean out well to CIPB @4200'. Drill out CIBP. Clean out to 4275'  | Contraction of the second seco |
| 3. Acid treat all perforations.  | 13 63 M and  |
| 4. Perform scale squeeze.  | S Strange  |
| 5. Run back in hole w/ESP equipment.   |  |
| 6. Return well to production.  | C. P. C. A.  |
|  | CA ZO AN   |
|  | 0-   |
|  | CLOZEL SI ZI SUSIT   |
|  |  |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief further certify the  | hat any pit or below-grade tank has been/will be   |
| constructed or   |  |
| closed according to NMOCD guidelines , a general permit or an (attached) alternative   | OCD-approved   |
| The set of the second plan   |  |
| SIGNATURE I NUNCLY U ADMON TITLE Administrative A  | Associate DATE 07/27/2007  |
| TYPE OR PRINT NAME Mendy A. Johnson E-mail address. mendy johnson@oxy.com  | TELEPHONE NO 806-592-6280  |
| For State Use Only   |  |
| APPROVED BY Haw Willink TITLE  |  |
|  | DATE   |
| CONDITIONS OF APPROVAL IF ANY  | Press Ward Burger Bra  |
|  | AUG 1 3 2007   |
|  |  |