UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

Form 3160-5	- :	TED STATES	and the same			APPROVED	
(February 2005)	DEPARTMENT OF THE INTERI		OR 31-123456		OMB NO. 1004-0137 Expires March 31, 2007		
	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON Do not use this form for proposals to drill or a abandoned well. Use Form 3160-3 (APD) for se		03031-123456700		5.\ Lease Serial No.		
	CHNDDY NOTICES	AND DEDODTS OF	N WEILE	~ / l\~;	DE020		
	SUNDAT NOTICES	AND REPORTS OF	AUG	2007	MMM26079 o. If Indian, Allottee or Tribe Name		
	Do not use this form for abandoned well. Use Form	eived is					
	abandoned wen. Ose Fon	11 3 100-3 (AF D) 101 3		the I	18		
	SUBMIT IN TRIPLICATE -	Other instructions	on reverse side	CD A	If Unit or CA/A	greement, Name and/or No.	
	30BINIT IN THIFLICATE	Other manachons (W. C. C. Legonia	Z6181 [D] 8.			
1. Type of Well			2125	76181			
X Oil Well	Gas Well Other	1	8.	8. Well Name and No. Ochoa Federal 1			
2. Name of Opera	itor		أداك خدر أفط يحي	C. C. Transcription	ma recera	1 1	
EOG Resour	rces Inc.		9.	API Well No.			
3a. Address		D1 11- (1 1 1 1-)		30-025-27623			
P.O. Box 2	2267 Midland, Texas 79702	432 686 3689		10. Field and Pool, or Exploratory Area			
	ell (Footage, Sec., T., R., M., or Survey				Mill; Bone Spring		
1979' FNL	& 1979' FEL						
Sec 15, T25S, R33E					1. County or Par	rish, State	
,		CON	CINTRID	A TE	эа	NM	
12	CHECK APPROPRIATE	BOX(ES) TO IND	CATE NATURE OF	OTICE, REPOR	T, OR OTHE	R DATA	
		1		PE OF ACTION			
IY	PE OF SUBMISSION		TIPE OF ACTION				
	Notice of Intent	Acidize	Deepen	Production (Sta	ırt/Resume)	Water Shut-Off	
L	1	Alter Cusing	Fracture Treat	Reclamation		Well Integrity	
x	Subsequent Report			H	Ī	<u> </u>	
		Casing Repair	New Construction	Recomplete		Other	
Final Abandonment Notice Change Plans			Plug and Abandon	Temporarily At	oandon <u>D</u>	rilled Lateral	
L	1	Convert to Injection	Plug Back	Water Disposal	1		
If the prop Attach the following of testing has determined 3/20/0 4/11/0 4/14/0 4/15/0 4/15/0 4/25/0 4/25/0 4/26/0 4/28/0 4/29/0	7 Preheat 5 1/2" casing s casing to 9000'. 7 POOH & laydown 70 jts 9 7 Finish pulling 5 1/2" of 7 Drill out composite bri 7 Finish cleaning out, fi 7 RIH w/ 2 7/8" production 7 RIH w/ 1 1/2" X 1 1/2"	bete horizontally, give sub- rformed or provide the sub- rformed or provide the sub- rformed or provide the sub- Notices shall be filed only ction.) bridge plug set (stub. Weld on 5 : 1/2" casing from casing. Prep to : dge plug and clea- low back to tanks on tubing set (1: X 26' pump and re	surface locations and meand No. on file with BLM and No. on file with BLM a multiple completion or after all requirements, in 11891. Prep to 1/2" casing couple m 9000' to 5900'. run in hole and dan cut.	sured and true vertical/BIA. Required subside completion in a new cluding reclamation, by o pull out of ing. POOH & lag	and depths of all pequent reports sinterval, a Formave been compared by the been compared by the been seen so the been seen seen seen seen seen seen see	ertinent markers and zones. shall be filed within 30 days a 3160-4 shall be filed once leted, and the operator has 1/2" casing. ts 5 1/2 2" casing.	
Name (Printe	Wagner Wagner		Date 05/07/0				
	// THI	S SPACE FOR FEDE	RAL OR STATE OF	FICE USE			
Approved by			Title		Date	-	

Office