	State of N	New Mexico		
	Energy, Minerals and N	atural Resources Department	nt	Form C-103 Revised 5-27-2004
FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		Keviseu 5-27-2004
DISTRICT 1		St. Francis Dr.	WELL API NO	
1625 N French Dr , Hobbs, NM 88240	' Santa Fe,	NM 87505	30-025-28879	
DISTRICT II		1	5 Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210		1	STATE X	FEE
DISTRICT III		. `	6 State Oil & Gas Lease No	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit Agreer	
	ORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A OIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals)		North Hobbs (G/SA) Unit Section 24	
1 Type of Well			8 Well No 414	
Oil Well	Gas Well Other In	jector		
2 Name of Operator			9 OGRID No 157984	
Occidental Permian Ltd. 3 Address of Operator			10. Deal nome of Weldoot	
HCR 1 Box 90 Denver City, TX	79323	•	10 Pool name or Wildcat	Hobbs (G/SA)
4 Well Location	19525			
Unit Letter A 10	Feet From The North	1280 Fee	t From The East	Line
				-
Section 24	Township 18-S	Range 37-E	; NMPM	Lea County
	3680' KB	(b, KT (b, elc)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
	Appropriate Box to Indicate Na			
	NTION TO:	SOBS	SEQUENT REPORT O	-:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ASING 18 70
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	IS DUG &	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	тјов 🔲 🖉 🖓	S. S.
OTHER.		OTHER: Squeeze/plug ba		in a los a
				
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1 RUPU & RU. Kill well. ND wellhead/NU BOP. 2. POOH w/tubing and injection equipment.				
3. Dump 30 5 gallon buckets of pea gravel. RIH w/ tubing & tag pea gravel @4197'. Dump 10 gallon of pea gravel down tubing. Tag pea gravel.				
@4190'. 4. RIH w/5-1/2" cement retainer to 4065'. RU HES Mix & pump 200 sxs of premium plus cement. 150 sxs below retainer Reverse out 46 sxs,				
leaving 4 sxs on top of retainer. Squeeze hole to 2500#. RD HES.				
5. RIH w/bit & drill collars to 4065'. RU power swivel. Drill out cement retainer @4065-67'. Drill cement from 4067-4190'. Clean out pea gravel				
from 4190-4325'. RD power swivel. POOH w/bit & drill collars.				
6. RIH w/5-1/2" treating packer set @4180'. RU HES & acid treat well w/3723 gal of NEFE acid, 1530 gal of brine, 4209 gal of fresh water w/1500# salt block in 3 stages. RD HES. POOH w/treating packer.				
sait block in 3 stages. RD HES, POOH		see additional data on attache	d sheet***	
I hereby certify that the information above is tru	ae and complete to the best of my know	ledge and belief further certify t	hat any pit or below-grade tank h	as been/will be
constructed or closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved	
monol A Doh and plan				
SIGNATURE	1 your your	TITLE Administrative		
	nson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO	806-592-6280
For State Use Only		and representation	tive hystaft mamake	AUG 1 6 2
APPROVED BY Nay W.	wink	TITLE	DAT	Ε
()				

AUG 1 6 2007

For State Use Only APPROVED BY Harry W. Wink CONDITIONS OF APPROVAL IF NY

ì



NHU 24-414

7. RIH w/5-1/2" 4 cup packer set @4180' & 5-1/2" HES G-6 packer set @4076' on 128 jts of 2-7/8" Duoline 20 tubing.

8. ND BOP/NU wellhead.

9. Test casing to 630# for 30 minutes and chart for the NMOCD

10. RDPU & RU. Clean location.

RUPU 07/09/2007 RDPU 07/18/2007



e in the second se

P128 1-1 24-4 14

.

the function

``