

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-30139
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1031
7. Lease Name or Unit Agreement Name: New Mexico 'AB' State
8. Well No. 9
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator 15 Smith Road - Midland, Texas 79705	4. Well Location Unit Letter <u>P</u> : <u>538</u> feet from the <u>South</u> line and <u>818</u> feet from the <u>East</u> line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM County <u>Lea</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3969' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: ☐ OTHER: Test Tbg, Change Out Pump, Swage Out Csg. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

09-09-03 MIRU. TOH w/rods; lay down k-bars and insert pump w/gas anchor.  
09-10-03 TOH w/2-7/8" prod tbg; tac hanging up @ 5400'; tried to work tbg free; no luck.  
09-11-03 Tag tight spot @ 5497' & worked pipe to try getting tac thru tight spot. TIH and tagged bottom @ 8990'. RIH w/ccl & chemical cutter; found tac @ 8108' to 8110'; cut tbg off @ 8093'. TOH w/prod tbg.  
09-12-03 Top of fish @ 8122'. PU 5-1/4" swage; went past tight spot @ 5497' to 5560'.  
09-15-03 TIH w/5-7/8" swage & WS to tag bad spot in casing @ 5468'.  
09-16-03 TIH w/5-3/8" swage, bumper subs, jars, dc & 2-7/8" tbg. Tagged bad spot in csg @ 5468' to 5470'. TOH w/5-3/8" swage. TIH w/5-1/2" swage, BH & tbg. Tagged & fell thru same bad spot @ 5468' to 5470'. TOH w/tbg to 4425'.  
09-17-03 TIH w/5-5/8" swage to tag tight spot @ 5468'; TOH; TIH w/5-3/4" swage to 1465'.

(CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Skinner TITLE Regulatory Specialist DATE 09-29-03

Type or print name Laura Skinner Telephone No. 432-687-7355

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE SEP 14 2003  
Conditions of approval, if any:

NEW MEXICO 'AB' STATE NO. 9  
PAGE 2

- 09-18-03 TIH to tag @ 5468'; worked swage thru tight spot & went down to 5530'; pass tight spot @ 5497'. TIH w/5-7/8" swage; tag @ 5468'.
- 09-19-03 Started swaging bad spot in casing @ 5468' to 5470' w/5-7/8" swage. TOH w/swage. TIH w/6" swage & tagged @ 5468'.
- 09-22-03 Tag bad spot in casing @ 5468' w/6" swage. Worked from 5468' to 5470'. Went down and tagged @ 5474'. TOH w/6" swage & TIH w/6-1/8" swage to 5430'.
- 09-23-03 TIH w/tbg to tag @ 5468' w/6-1/8" swage; swaged from 5465' to 5471'.
- 09-24-03 Worked 6-1/8" swage from 5471' to 5472'; fell thru to 5482' & worked to 5483'.
- 09-25-03 Started swagging w/6-1/8" tool @ 5483'; fell thru. TOH w/swage. TIH w/5-3/4" overshot, bumper subs, new jars, dc & 2-7/8" WS to 5400'.
- 09-26-03 TIH w/2-7/8" WS & tagged @ 8093'. Latched on to fish & had to hit jars one time to pull fish off bottom. TOH w/tbg & hang tac up @ 5985'; worked it loose; TOH to get hang up again @ 5497'. Lay down fish.
- 09-27-03 TOH w/kill string. TIH w/dc & TOH laying down tools. TIH w/tbg & TOH laying down work string. TIH w/2-7/8" prod tbg to 945'.
- 09-29-03 TIH w/mud anchor, perf sub, new SN, blast jt. & tac. TIH w/2-7/8" prod tbg and tested (good). Set tac @ 7941'.
- 09-30-03 TIH w/gas anchor, insert pump, lift sub, k-bars, rods, sub & polish rod w/liner. Load and test to 500# (good). Good pump action. Rig Down. FINAL REPORT.

