

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-09855

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ X OTHER SWD

2. Name of Operator
Southwest Royalties, Inc.

3. Address of Operator
P.O. Box 11390, Midland, TX 79702 432-686-9927

4. Well Location
Unit Letter P : 330' Feet From The South Line and 990' Feet From The East Line

Section 13 Township 26S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 9-16-03 MIRU.
2. 9-17-03 Spot 150 sx cmt. @ 3122', WOC & tag @ 3122'.
3. 9-18-03 Spot 150 sx cmt. @ 3122', WOC & tag @ 2856'.
4. 9-18-03 Spot 50 sx cmt. @ 2856', pressure test csg. 500# okay.
5. 9-19-03 Cut & pull 10-3/4" from 1400'.
6. 9-22-03 Spot 100 sx cmt. @ 1450' WOC & tag @ 1295'.
7. 9-23-03 Cut 13" csg. @ 600', could not pull csg. stuck.
8. 9-23-03 Cut 13" csg. @ 550', could not pull.
9. 9-23-03 Spot 150 sx cmt. @ 650' to 500', WOC.
10. 9-24-03 Tag TOC @ 575', spot 75 sx WOC & tag @ 475'.
11. 9-24-03 Perf. 13" X 16" csg. @ 100', spot 200 sx cmt. w/ no returns WOC.
12. 9-25-03 Perf. @ 75', spot 100 sx cmt. fill csg. from 75' to surface.
13. RDMO. Cut off wellhead, install dry hole marker, & clean location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. Massey TITLE Agent DATE 10-07-03

TYPE OR PRINT NAME Roger Massey Donna Howard TELEPHONE NO. 432-530-0907

(This space for State Use)

OC DISTRICT SUPERVISOR/GENERAL MANAGER

APPROVED BY Harry W. Wink TITLE 10/10/03 DATE OCT 16 2003

CONDITIONS OF APPROVAL, IF ANY: