

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <u>30-025-21704</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: <u>Mohar State</u>
8. Well No. <u>1</u>
9. Pool name or Wildcat <u>Mescalero San Andres</u>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

PENROC OIL CORPORATION

3. Address of Operator

P.O. Box 2769, Hobbs, NM 88241

4. Well Location

Unit Letter I : 1650 feet from the South line and 330' feet from the East line

Section 10 Township 10S Range 32E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

4330' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

10-3-03 - 10-8-03

RU. Pulled & LD rods & pump. TOH w/ tubing. RU wireline - Ran gauge ring to 4050' - O.K. Set CIBP @ 4025'. DUMPED 45' cement on top. Perforate 2 holes @ 1600'. TOH w/ 128 jts of 2 1/8" tbg. Displace hole w/ gelled brine. TOH & TCH w/ 4 1/2" pkr. Sparged holes w/ 30 psi. WOC. TCH & tbg plug @ 1461'. TOH to 440' and pumped 25 hrs. to surface, RD Rig. Cut off well head. Installed dry hole marker. Cut off dead man - clean location. Job complete. OCD field rep. witnessed (Billy Archard).

Approved as to plugging of the Well Bore.

Liability under bond is retained until the best of my knowledge and belief surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: M. Y. Merchant TITLE: President DATE: 10-10-03

or print name M. Y. Merchant Telephone No. (505) 492-1236

APPROVED BY: Larry W. Wink TITLE: OCD DISTRICT SUPERVISOR/GENERAL MANAGER DATE: OCT 16 2003

Conditions of approval, if any: