

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36329
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> P <input type="checkbox"/>
2. Name of Operator Pecos Production Company		6. State Oil & Gas Lease No.
3. Address of Operator 400 W. Illinois, Suite 1070, Midland, TX 79701		7. Lease Name or Unit Agreement Name Lou Wortham
4. Well Location Unit Letter <u>E</u> : <u>1650'</u> feet from the <u>North</u> line and <u>990'</u> feet from the <u>West</u> line Section <u>11</u> Township <u>22S</u> Range <u>37E</u> NMPM Lea County		8. Well Number 7
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3365' GR		9. OGRID Number 215758
		10. Pool name or Wildcat Eunice; San Andres, South

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Complete Well & Turn Over To Production ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/6/03- RIH w/bit & tag PBTD @ 4742'.

8/7/03- Displace hole w/2% KCl. Log. Perf Lower San Andres 4597', 4609', 4630'-34' w/2 SPF. Swab.

8/8/03- Swab.

8/11/03- Swab. Acidize perms w/1000 gals 15% FEAS2X + 28 BS. LD & test tbg to 1500 psi- Ok. Set pkr @ 4515' & test annulus to 750 psi- Ok. Swab.

8/12/03- Swab test.

8/14/03- Perf Upper San Andres 4108'-4248'. RIH w/RBP & set @ 4300'. Test RBP to 2000 psi- Ok.

8/15/03- RU Halliburton & acidize perms w/7500 gals Hot CCA Sour well acid w/AS-5, HAI-GE & FE8 + 56 BS. Swab well.

8/18/03- Swab. Unset pkr & RBP & ran 2 7/8" tbg & set tbg @ 4675.68'.

8/19-23/03- Set pumping unit & lay FL to btry.

9/15/03- POOH w/rods & pmp. Prep to perf. Perf w/1 SPF (36-.45" holes) from 3876'-4055'. Set RBP @ 4094' & pkr @ 4079'. Test to 2500#. Set pkr @ 3809' & test csg to 650#.

9/16/03- Acidize perms w/7500 gals 15% HCl acid w/60 BS's. Swab.

9/17/03- Swab. Rls pkr & retrieved RBP. RIH w/prod tbg & set @ 4671'. RIH w/rods & pmp. Test pmp. RDMO. Turn well over to production.

9/24/03- Test - 26 BO, 64 BW & 81 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora B. Lara TITLE Engr Asst. DATE 9/24/03

Type or print name Dora B. Lara E-mail address: dorab@pecosproduction.com Telephone No. 432-620-8480

(This space for State use)

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE OCT 17 2003

Conditions of approval, if any: