State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISI	ON		1001300 5 27 2001	
DISTRICT I	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API 1		-	
1625 N. French Dr , Hobbs, NM 88240				30-025-38023		
DISTRICT II			5 Indicate	Type of Lease		
1301 W Grand Ave, Artesia, NM 88210				STATE X	FEE	
DISTRICT III			6 State Oil	& Gas Lease No		
1000 Rio Brazos Rd, Aztec, NM 87410	TICES AND REPORTS ON WE	110	7 Lease Na	me or Unit Agreer	nent Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				-		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)				North Hobbs (G/SA) Unit Section 13		
1. Type of Well			8 Well No	516		
Oil Well X Gas Well Other				510		
2 Name of Operator			9. OGRID N	lo. 157984		
Occidental Permian Ltd.						
3 Address of Operator			10 Pool nar	ne or Wildcat	Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX 4. Well Location	. 19323					
	Fast From The Could	1075	East Erem The		1	
Unit Letter <u>M</u> 480	Feet From The South	1275	Feet From The	West	Line	
Section 13	Township 18-S	Range	37-E NI	мрм	Lea County	
	11. Elevation (Show whether DF, RI	KB, RT GR, etc)				
	3677' GL					
Pit or Below-grade Tank Application	or Closure					
Pit Type Depth of Ground		earest fresh water well	Distance	from nearest s	irface water	
Pit Liner Thickness mil	Below-Grade Tank: Volume			inom nearest st		
	Below-Grade Talik. Volume		non material			
12. Check	k Appropriate Box to Indicate Na	ture of Notice, Repo	ort, or Other Data			
NOTICE OF INT	ENTION TO:		SUBSEQUENT	REPORT O	F:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.						
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND		ן בפסמ <i>ו</i> ר		
·				_		
OTHER Plug back/Perforate/Acid		OTHER	······			
13. Describe Proposed or Completed Ope	erations (Clearly state all pertinent de	etails, and give pertine	nt dates, including es	imated date of s	tarting any	
proposed work) SEE RULE 1103.	For Multiple Completions: Attach w	ellbore diagram of pro	posed completion or	recompletion.		
1. Kill well. Pull the production equip	pment					
2. Clean out to PBTD				49192	2021	
3. Plug back.				617 10 ·		
4. Perforate @4225-41', 2 JSPF.				15 6		
 1. Kin wen. Fun the production equipment. 2. Clean out to PBTD 3. Plug back. 4. Perforate @4225-41', 2 JSPF. 5. Acid treat the well. 6. Run back in hole w/production equipment. SEP ```						
S. Kur back in note w/production equipment.						
			6	e Rec	Wee N	
				5 4		
			,	16	c.0	
I hereby certify that the information above is t	min and complete to the bast of the l			<u></u>	.c.0°/	
constructed or	rue and complete to the best of my knowl	ledge and belief. I further	certify that any pit or b	elow-gradestanken	e been/will be	
closed according to NMOCD guidelines	, a general permit	or an (attached) alt	ernative OCD-approv	red		
m.		plan				
SIGNATURE NUNCLY	. all throw	- TITLE Adminis	trative Associate	DATE	09/18/2007	
TYPE OR PRINT NAME Mendy A. Jo						
	hnson / /F-mail address	mendy johnson@o	VV com	ELEPHONE NO	206 502 6200	
For State Lise Only	hnson / E-mail address:	mendy_johnson@ox	<u>ky.com</u> 1	ELEPHONE NO.	806-592-6280	
For State Use Only		oc aeld astres				
For State Use Only APPROVED BY CONDITIONS OF APPROVAL IF ANY		mendy_johnson@o; OC_PIELD_&EPRES			806-592-6280 SEP 2 0 2007	