

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd , Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-08858
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A A/C 2
8. Well Number 39
9. OGRID Number 194849
10. Pool name or Wildcat Eunice 7 Rvrs Queen South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other	
2. Name of Operator Petrohawk Operating Company	
3. Address of Operator 1000 Louisiana, Suite 5600 Houston TX 77002	
4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line Section <u>9</u> Township <u>22S</u> Range <u>36E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567 GL	
Pit or Below-grade Tank Application ☐ or Closure ☐	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS ☐ P AND A ☒ CASING/CEMENT JOB ☐ OTHER: ☐
--	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Run wireline & dump bail 35 cmt on CIBP @ 3650'. Run wireline & perf @ 3010'. Run tbg pkr @ 3500' & circulate hole w/ 10 ppg gel. Pull tbg & set pkr @ 2600'. Pressure up on perf @ 3010' to 2250#, unable to pump into perf. Notify OCD/El Gonzales, he request us to spot 35 sks cmt 3060'-2860'. WOC. Spot 35 sks cmt 3060'-2860'. Pull tbg. Run tbg tag TOC @ 2835'. Pull tbg. Run wireline & perf @ 1680'. Run tbg, pkr. Squeeze perf 1680' w/ 70 sks cmt & displace to 1480', WOC. Run tbg & tag TOC @ 1430'. Pull tbg. Run wireline & perf @ 275'. Pump 100 sks cmt dn csg & circulate cmt out surface. Hole standing full. Cut off wellhead & anchors. RDMO.

08/30/2006

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE _____ TITLE Production Foreman DATE 9-20-07

Type or print name Joel Sisk E-mail address: jsisk@petrohawk.com Telephone No. 505-394-2574
For State Use Only

APPROVED BY: Gary W. Wink OC FIELD REPRESENTATIVE w/ STAFF MANAGER OCT 01 2007
Conditions of Approval (if any): _____ TITLE _____ DATE _____