

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis, Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-025-26863
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-1597	
7. Lease Name or Unit Agreement Name East Vacuum GB/SA Unit Tract 3127	
8. Well Number 006	
9. OGRID Number 217817	
10. Pool name or Wildcat Vacuum Grayburg/San Andres	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other Water Injection

2. Name of Operator  
ConocoPhillips Company

3. Address of Operator 4001 Penbrook Odessa TX 79763

4. Well Location

Unit Letter J : 1330' feet from the South line and 1530' feet from the East line

Section 31 Township 17S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3976' RKB 3965' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐


OTHER: Convert to WAG Well ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-4-03 - ND Wellhead, NU BOP, POOH with tubing and packer. POOH with tubing, scraper and bit. Finish cleaning out fill.

9-9-03 - POOH with tubing, collars and bit. TIH with packer, on/off tool and tubing. ND BOP, NU Wellhead. Test casing/packer to 500 psi for 30 mins.

Held good. Put well back on injection. A MIT chart is attached.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kristy S. Ward TITLE Regulatory Assistant DATE 10/15/2003

Type or print name Kristy S. Ward


Telephone No. (432)368-1371

(This space for State use)

APPROVED BY Larry W. Wink TITLE DISTRICT SUPERVISOR/GENERAL MANAGER

OCT 21 2003  
DATE

Conditions of approval, if any



VACUUM GRAYBURG SAN ANDRES UNIT  
3127-006  
TSL 1530 FFL  
TSL 125 R35 F  
API 30-025-24863  
LEI COUNTY NEW MEXICO