Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240	8240		WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	esia, NM 88210 OIL CONSERVATION DIVISION		30-025-36164 5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE	FEE K
1000 Rio Brazos Rd., Aztec, NM 87410		505	6. State Oil & Ga	
District IV 1220 S. St. Francis Dr., Santa Fe, NM			o. State Off & Ga	s Lease No.
87505				State of the second
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:			7. Lease Name or Unit Agreement Name:	
Oil Well X Gas Well Other			LIBERTY 4	
2. Name of Operator			8. Well No.	
READ & STEVENS, INC.			3	
3. Address of Operator			9. Pool name or Wildcat	
P. O. BOX 1518 ROSWELL, NM 88202			<u> </u>	
4. Well Location				
Unit Letter E : 2	2310 feet from the NORTH	line and	660 feet from	the <u>WEST</u> line
Section 4	Township 20S Ra	inge 36E	NMPM	County LEA
	10. Elevation (Show whether DI			
3,630' GL				
11. Check A ₁	ppropriate Box to Indicate N	ature of Notice.	Report or Other I	Data
			SEQUENT REP	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING
The state of the s			`	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			LLING OPNS. 🗌 📁	PLUG AND KINA ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AN COMPLETION CEMENT JOB			1D 🗆	
OTHER:		OTHER:		П
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
	2 @ 4,250'. Dump bail 35' cr	nt on top of CIBI	P. Cut csg @	
@ 1,050'.				
07/03/03 RIH w/ 133 jts 2 7/8" tbg to 4,200'.				
Displace hole w/ 9# mud. EOT @ 1,570'.				
Pump 35 sx cmt, plug @ 1,570'. Lay down tbg to 1,100'.				
Pump 65 sx cmt, plug @ 1,100'. Lay down tbg to 445'.				
Pump 65 sx cmt, plug @ 445'. Lay down tbg to 95'.				
Pump 65	5 sx cmt, plug @ 95'. Circ cr	nt to surface. A	unnoved as tooplug	ging of the Well Bore
Complete	e laying down tbg, cut csg he		iability under bond	
Install dr	y holer marker. Reseed to r			
	ified & present.	- 51	urface restoration is	s-completed.
	·		100), AD
				Let Stardtare, 1713
I hereby certify that the information al	pove is true and complete to the be	est of my knowledge	e and belief.	
SIGNATURE STATES	TITLE	OPERATIONS M	ANAGER	DATE 10-16-03
Type or print name JOHN C.	MAXEY, JR		Telepho	one No. 505/622-3770
(This space for State use)	. 1			
\mathcal{U}_{-1}	$(11) \sim b$	TOT CLINEDING	GENERAL MANAG	ER OCT O 4 FEE
APPPROVED BY Wary	U-WUNK TOTTLEIST	RIGI PHLEKAIDAK	, ()	DA UE T 2 1 2003
Conditions of approval, if any	. •			