

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Ave , Artesia, NM 88210
District III
1000 Rio Brazos Rd , Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-08836
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A A/C 2
8. Well Number 37
9. OGRID Number 194849
10. Pool name or Wildcat Jalmat, Tansill, Yates, 7 rvs, Gas 79240

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Petrohawk Operating Company	
3. Address of Operator 1000 Louisiana, Suite 5600 Houston TX 77002	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>8</u> Township <u>22S</u> Range <u>36E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application ☐ or Closure ☐	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☒ CASING/CEMENT JOB ☐ OTHER: ☐
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-4-07 DO CIBP @ 3097' & CO to 3760'.

9-12-07 RU Pluggers. Inform Buddy Hill & he OK. Set 4 1/2" CIBP @ 3800' & dump bail 35' cmt. Set 5 1/2" CIBP @ 3110'. Gel hole & spot 25 sks cmt 3110'-2869'. WOC. Tag TOC @ 2906'. Inform Buddy Hill & he ok. Spot 30 sks cmt 2700'-2411'. WOC. Tag TOC @ 2615'. Inform Maxie Brown & he OK. Spot 25 sks cmt 2615'-2374'. WOC. Tag TOC @ 2389'. Maxie Brown OK. Perf @ 1600'. Squeeze perf 1600' w/ 100 sks cmt & displace to 1375'. WOC. Tag TOC @ 1371'. Perf @ 255'. Squeeze perf @ 255' w/ 150 sks cmt. Did not circulate cmt. WOC. Tag TOC @ 45'. Inform Maxie Brown & he OK. Fill csg w/ cmt. Cut off wellhead & anchors. Weld on dry hole marker. Request PA status for well.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Joel Sisk TITLE Production Foreman DATE 10-2-07

Type or print name Joel Sisk E-mail address: jsisk@petrohawk.com Telephone No. 505-394-2574

For State Use Only

APPROVED BY: Gay W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 09 2007
Conditions of Approval (if any):