

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-09298
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A A/C 1
8. Well Number 89
9. OGRID Number 194849
10. Pool name or Wildcat Jalmat, Tansill, Yates, 7 rrvs, Gas

4. Well Location Unit Letter <u>N</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>10</u> Township <u>23S</u> Range <u>36E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3417 GR
Pit or Below-grade Tank Application ☐ or Closure ☐
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8-29-07 Pull RBP @ 3166' & 3180'.

9-4-07 RU Pluggers. Inform Buddy Hill & he OK. Spot 120 sks cmt 3490'-2795'. WOC. Tag TOC @ 2790'. Circulate hole w/ gel brine. Spot 35 sks cmt 2790'-2595'. Inform Buddy Hill hole standing full. He OK. Perf @ 1270'. Squeeze perf @ 1270' w/ 65 sks cmt & displace to 1070'. WOC. Tag TOC @ 1072'. Perf @ 370'. Squeeze perfs @ 370' w/ 205 sks cmt. Circulate cmt to pit. WOC. Tag TOC @ 92'. Inform Buddy Hill & he OK. Fill csg w/ cmt to surface w/ 20 sks. Cut off wellhead & anchors. Weld on dry hole marker. Request PA status.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Joel Sisk TITLE Production Foreman DATE 10-2-07

Type or print name Joel Sisk E-mail address: jsisk@petrohawk.com Telephone No. 505-394-2574

For State Use Only

APPROVED BY: Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 09 2007
Conditions of Approval (if any):