

Form 3160-3
(April 2007)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

S

FORM APPROVED
OAR 9/1/2004
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other	OCT 05 2007	2. Lease Serial No. NMNM71874
3. Name of Operator Xeric Oil & Gas Corp.	OCD-ARTESIA	3. If Unit or Co. Agreement, Name and or No. NM 71874
4. Address P.O. Box 7288 Odessa, Tx. 79760	432-664-0981	5. Well Name and No. Crosby Deep #2
6. Location of Well (Feet or Sec. T. R. M. or Survey Description) Section 33 Township 25S Range 37E	1650' N 8 230' E	9. API Well No. 30-025-24287
		10. Field and Pool, or Exploratory Area Crosby Deep Fusselman
		11. County or Parish, State Lea Co. NM

12. CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☒ Notice of Intent	☐ Abandon
☐ Subsequent Report	☐ Alter Casing
☐ Final Abandonment Notice	☐ Casing Repair
	☐ Change Plans
	☐ Consent to Injection
	☐ Deepen
	☐ Fracture Treat
	☐ New Construction
	☐ Plug and Abandon
	☐ Plug Back
	☒ Production (Start/Resume)
	☐ Reclamation
	☐ Reconveyance
	☐ Temporarily Abandon
	☐ Water Disposal
	☐ Water Shut-Off
	☐ Well Integrity
	☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletes horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-3 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Check for H₂S, Call for electrician to hook up pump, check well head for any problems, check flow lines with hydro tester, service sub pump, turn well on. After testing well for a few days as to volume make decision to continue or plug back to a zone above. Reperforate new zone, test and or plug /abandon, have BOP on location if or when needed

No H₂S data - requested 5/10 & 7/5/07

14. I hereby certify that the foregoing is true and correct
Name (Printed, Typed)

Walter E. King

Title

Vice President

Signature

Date

Walter E. King

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

OCT 3 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

WESLEY W. INGRAM
PETROLEUM ENGINEER

File 18 U.S.C. Section 1001 and Title 42 U.S.C. Section 1292 make it a crime for any person knowingly and willfully to make or knowingly cause to be made or knowingly cause to be made any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Instructions on page 2

GWW