

Form 3160-5
(April 2004)UNITED STATES **OCD-HOBBS**
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OAR No. 10044137
Effective March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other
 2. Name of Operator
Xeric Oil & Gas Corp.
 3a. Address
P.O. Box 7288 Odessa, Tx. 79760
 3b. Phone No. (Include area code)
432-664-0981
 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Section 33 Township 25S Range 37E

5. Lease Serial No.
NMNM71874 LC054667
 6. If Indian, Allottee or Tribe Name
Private
 7. If Unit or C/A Agreement, Name and/or No.
NM 71874
 8. Well Name and No.
Crosby Deep #4
 9. API Well No.
30-025-25985
 10. Field and Pool, or Exploratory Area
Crosby Deep
 11. County or Parish, State
Lea Co. NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☒ Notice of Interm	☐ Acidize
☐ Subsequent Report	☐ After Casing
☐ Final Abandonment Notice	☐ Casing Repair
	☐ Change Plans
	☐ Convert to Injection
	☐ Deepen
	☐ Fracture Treat
	☐ New Construction
	☐ Plug and Abandon
	☐ Plug Back
	☒ Production (Start/Resume)
	☐ Reclamation
	☐ Recomplete
	☐ Temporarily Abandon
	☐ Water Disposal
	☐ Water Shut-Off
	☐ Well Integrity
	☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-5 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Check H2S, check power, dress up location, call electrician to install transformer, turn well on, evaluate, make decision to continue with original perfs or reperforate new zone at 8612-8630 and one at 8640-8670. Then check another zone at 5276 then a possible at 8024-8038 but looks tight. We will run a Neutron Log (cased hole) to check possible hydrocarbon and at that point decide where to continue.

No H2S data - contacted

14. I hereby certify that the foregoing is true and correct
 Name (Printed/Typed)

Walter E. King

Signature

Walter E. King

Title Vice President

Date

Walter E. King

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

OCT 3 2007

WESLEY W. INGRAM

ENGINEER

Title 18 U.S.C. Section 901 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW