Submit 3 Copies To Appropriate District State of New Mexico	Form C-10
Office Energy, Minerals and Natural Resources	May 27, 200 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240	WELL API NO. 30-025-07584
District II 1301 W. Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	
1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505	
District IV 1220 S St Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	South Hobbs GSA Unit
1. Type of Well:	8. Well Number
Oil Well Gas Well Other Water injector	37
2. Name of Operator	9. OGRID Number
BP America Production Company	778
3. Address of Operator	10. Pool name or Wildcat
501 Westlake Park Blvd.; Houston, TX 77079	Hobbs Grayburg - San Andres
4. Well Location Unit Letter <u>G</u> : <u>1980</u> feet from the <u>North</u> line and <u>Section</u> <u>3</u> Township 19-S Range 38-E	2310 feet from the East lin
Section 3 Township 19-S Range 38-E 11. Elevation (Show whether DR, RKB, RT, GR, e	
II. Elevation (Snow whether DK, KKB, KT, OK, e 3616' DF	2420-2420-2-
Pit or Below-grade Tank Application or Closure	AN A TED
Pit type Depth to Groundwater Distance from nearest fresh water well D Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construct	istance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construct	ion Material
the second s	D BBCChe
12 Check Appropriate Box to Indicate Nature of Notice	, Report, or Other Data
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ALTERING OPNS.
	ALTERING OPNS.
NOTICE OF INTENTION TO: SUPPREFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE	ALTERING OPNS.
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	ALTERING CASING LING OPNS. ve pertinent dates, including estimated date
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion.	ALTERING OR ALTERING OASING LING OPNS. PLUG AND ABANDONMENT D
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995.	ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'.	BSEQUENT REPORT OF: ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" an
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" an ent between the 7" and 12-1/2". Cap
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIEP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'.	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" an ent between the 7" and 12-1/2". Cap
NOTICE OF INTENTION TO: SUPERFORM REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" an ent between the 7" and 12-1/2". Cap
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIEP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of Well P&A 06/21/1995.	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" an ent between the 7" and 12-1/2". Cap
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIEP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of	ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT O ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and amt between the 7" and 12-1/2". Cap Ef wellhead.
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of Well P&A 06/21/1995.	BSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and ant between the 7" and 12-1/2". Cap Ef wellhead.
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. OTHER: P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIEP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of Well P&A 06/21/1995. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelings a general permited	BSEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and ant between the 7" and 12-1/2". Cap Ef wellhead.
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. OTHER: P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of Well P&A 06/21/1995. Thereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines a general permit SIGNATURE Automation above is true and complete to the best of my knowled	ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and ent between the 7" and 12-1/2". Cap Ef wellhead. ge and belief. I further certify that any pit or below itor an (attached) alternative OCD-approved plan <u>Representative</u> DATE <u>10/18/2007</u>
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. OTHER: P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of Well P&A 06/21/1995. Thereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines a general permit SIGNATURE Automation above is true and complete to the best of my knowled	BSEQUENT REPORT OF: ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ALTERING CASHG ABANDONMENT D ve pertinent dates, including estimated date ch wellbore diagram of proposed completion .5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and ent between the 7" and 12-1/2". Cap Ef wellhead. ge and belief. I further certify that any pit or below itor an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: SUP PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER: P&A operations began 06/12/1995 and were completed on 06/21/1995. MIRU. Set CIBP @ 3970' and cap w/50' class C cmt. Loaded hole w/9. plug f/2590'-2690'. Spot 100' class C cmt plug f/1580'-1680'. Perf 7" casing. Set cement retainer @ 200' and circulated 150 sacks ceme w/ 10 sacks class C cement f/0-10'. Installed P&A marker and cut of well P&A 06/21/1995. Thereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permits SIGNATURE MIRU. FILL Permitting -E-mail address:	BSEQUENT REPORT OF: ALTERING CASING ALTERING CASING LING OPNS. ALTERING CASING PLUG AND ABANDONMENT ve pertinent dates, including estimated date ch wellbore diagram of proposed completion 5# mud brine. Spot 100' class C cmt E 300' w/4 spf to penetrate the 5" and ent between the 7" and 12-1/2". Cap Ef wellhead. ge and belief. I further certify that any pit or below itor an (attached) alternative OCD-approved plan <u>Representative</u> DATE <u>10/18/2007</u> leah.brumlowebp.com Telephone No. (281) 366-C