

District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30 025 28330
1. Type of Well: Oil Well ☒ Gas Well ☐ Other (Injection) ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Shinnery Oil Co., Inc.		6. State Oil & Gas Lease No. K 3290
3. Address of Operator 606 W. Tennessee, Suite 107, Midland, TX 79701		7. Lease Name or Unit Agreement Name Baum "E" State
4. Well Location (Surface) Unit Letter <u>F</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>9</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>Lea</u> County		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.): <u>4240.4</u>		9. OGRID Number 20713
10. Pool name or Wildcat Baum, Upper Penn		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
 OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**THE OIL CONSERVATION DIVISION MUST
 BE NOTIFIED 24 HOURS PRIOR TO THE**

Propose to P & A as follows:

1. CIBP @ 9750 w/35' cement on top, tag.
2. Cut & pull 5 1/2" casing @ 8000', 30 sx plug - 50' above & below csg cut, tag.
3. 40 sx plug 4144-4244' (8 5/8" casing @ 4194'), tag
4. 50 sx plug from 1400-1500', tag.
5. Cut & pull 8 5/8" casing @ 1000' (TOC on 8 5/8" 1050' by Temp Survey), 50 sx plug, tag.
6. 80 sx plug from 323-423', (13 3/8" @ 383'), tag.
7. 10 sx plug @ surface - WOC & set P & A Marker.
 Class C/Poz cement or type as specified by OCD.
 Wellbore Diagram attached.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE: 10-17-07

Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381

(This space for State use) OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY Gay W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE 10-26-2007

Conditions of approval, if any:

OCT 26 2007

Baum "E" State #2

1980' FNL + 1980' FWL

Well bore -
Proposed
P & A

GL
Elev. @ 4240'

Sec 9, T-14-S, R-33E

TD @ 10,100'

Lea Co. NM

PBTD @ 10,081'

SPUD 9-17-83

Surface

10 SX

17 1/2"

Hole

~80 SX

TAG plug

323

H 23

13 3/8" csg set @ 383' cement
w/ 425 SX. 54.5# H-40) Circ

cut & Pull ~ 1000'
50 SX plug TAG

TOC @ 1050' by Temp Survey

40 SX plug 50' above Salt
1500' to 1400'

11"

Hole

1400'

40 SX

1500'

TAG ~40 SX
plug

4144'

4244'

8 5/8" csg set @ 4194' cement
w/ 1500 SX. (28# + 32# - K-55)
TOC @ 1050' by T.S.

W/ stretch
csg -

determine
Free pt

cut & Pull @ 8000'

50' Above & Below csg cut
~30 SX

TOC @ 8920' by Temp Survey

7 7/8"

Hole 35' cmt on
CIBP @ 9750'

TAG

9715'

Penn Perfs 9848-9910

Penn Perfs 9955-9990

5 1/2" csg set @ 10,100'
cement w/ 300 SX

(15.5# + 17# N-80)
K-55

TD @ 10,100'