State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION	
<u>DISTRICT I</u> 1625 N French Dr , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO 30-025-05440
DISTRICT II	·		5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210			STATE X FEE
DISTRICT III			6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410			
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals)			Section 13
1 Type of Well Oil Well		emporarily Abandoned	8 Well No 121
2 Name of Operator			9 OGRID No 157984
Occidental Permian Ltd. 3 Address of Operator			10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T	X 79323		110003 (0/8/1)
4. Well Location	X 17323		
Unit Letter E 1980	Feet From The North		t From The West Line
Section 13	Township 18-S	Range 37-E	NMPM Lea County
	11 Elevation (Show whether DF, RK 3692' DF	(B, RT GR, etc)	
Pit or Below-grade Tank Application	or Closure		
		nearest fresh water well	Distance from nearest surface water
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
Pit Liner Thickness mil	Below-Grade Tank: Volume	Dois, Construction wa	neriai
12. Chec	ck Appropriate Box to Indicate Na FENTION TO:		Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB
OTHER. Repair casing leak	X	OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Pull equipment. 2. Locate leak.			
1. Pull equipment.			
2. Locate leak.			(3) []
3. Perform repairs as required. 4. Notify NMOCD of pressure test. 5. Run equipment. 1. Notify NMOCD of pressure test. 1. Notify NMOCD of pressure test.			
4. Notify NMOCD of pressure test.			
5. Run equipment.			
			Received 45 OCD
			(10)
			SIFIELTIVE
			that any pit or belowgrade tank has been/will be
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or			
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan			
SIGNATURE / herdy	Cashnon	TITLE Administrative	Associate DATE 10/25/2007
TYPE OR PRINT NAME Mendy	Johnson E-mail address:	mendy_johnson@oxy_com	TELEPHONE NO 806-592-6280
For State Use Only		CHELD DEPRESENTATI	ve histafp maklages
APPROVED BY Hauli	I will	TITLE	DATE OCT 9 C 2007